



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO20011358/Utf3e2-1	
			Date: 23/12/2020	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 2686L	Veh. Inspected	SKB 6484G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2003053/MYE	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	17/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN SYLPHY (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	JN1BAAG11Z0150317	Colour	BROWN	
Odometer	264645 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	5 mm	
L/H Front Tyre	195/65 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2020	Inspection Date	20/10/2020	
Survey held at	A S AUTO SERVICE NO 1 KAKI BUKIT #01-106 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	