

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

2/3

Mr
LOW
HAN SIONG
7 VERDE PLACE
Singapore 688617

Document no.
Document date 15-12-2020
Customer no. 5211035173
Customer GST-ID
Dealer 30001
Job order number 2020034525/ 1
Job order date 14-12-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SLG6352R	5G13HZ	07-10-2016	VWVZZZAUZHW057969	Golf 1.4 CLBM 92 TSI D7F	52,906

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G0821135B	Cross Support	1	pcs.	31.68	#1	31.68	33.90
N 90817302	FENDER BRACKET LH <i>3bt</i>	4	pcs.	2.23	#1	8.92	9.54
5G0805911AK	Rivetted Cap Nut <i>ne</i>	1	pcs.	84.97	#1	84.97	90.92
5G0805969P	Wheelhouse Liner <i>3 X SUC</i>	1	pcs.	181.47	#1	181.47	194.17
5G0821111C	LHS FENDER LINER (LOWER) <i>3cm</i>	1	pcs.	47.36	#1	47.36	50.68
5G0864237H	Sound Absorber For Fender <i>3de</i>	1	pcs.	15.07	#1	15.07	16.12
5G4809835	LHS FENDER ELEMENT <i>3 X SUC</i>	1	pcs.	1,010.92	#1	1,010.92	1,081.68
N 90817302	Sectional Part-Pillar A/B <i>bt</i>	2	pcs.	2.23	#1	4.46	4.77
N 10009110	Rivetted Cap Nut <i>ne</i>	2	pcs.	2.19	#1	4.38	4.69
D 506KD1A4	Bolt Hex. Hd <i>ne</i>	1	pcs.	144.94	#1	144.94	155.09
D 476KD1M2	2k-Füllschaum <i>ne</i>	1	pcs.	61.67	#1	61.67	65.99
D 007500A2	Sealant Can Be Sprayed <i>ne</i>	1	pcs.	62.88	#1	62.88	67.28
D 180003M2	Zinc Spray <i>ne</i>	1	pcs.	406.76	#1	406.76	435.23
5G2857507DN9B9	2k-Body Adhesive <i>ne</i>	1	pcs.	562.83	#1	562.83	602.23
5G0857537E GRU	Rear View Mirror Housing <i>X SUC</i>	1	pcs.	167.56	#1	167.56	179.29
5G0857521A	LHS MIRROR HOUSING <i>3</i>	1	pcs.	180.70	#1	180.70	193.35
5G4831055AS	Mirror Cap Primed <i>- repair</i>	1	pcs.	2,004.50	#1	2,004.50	2,144.82
7L6868243	Door	6	pcs.	1.49	#1	8.94	9.57
D 378500A2	LHS FRT DOOR <i>3bt</i>	1	pcs.	41.40	#1	41.40	44.30
5G4837651B	Clip <i>3ne</i>	1	pcs.	103.28	#1	103.28	110.51
533867910A	DOOR BOARD CLIP <i>3ne</i>	1	pcs.	19.82	#1	19.82	21.21
8K0831401D	Sound Absorber Laminated <i>3ne</i>	1	pcs.	129.72	#1	129.72	138.80
N 90365913	DOOR INSULATOR	1	pcs.	2.76	#1	2.76	2.95
5G0601025AFZ49	Door Seal <i>ne</i>	2	pcs.	1,337.14	#1	2,674.28	2,861.48
311601361	Felt Strip <i>ne</i>	2	pcs.	3.29	#1	6.58	7.04
CINTURATO	Door Hinge <i>3 X SUC</i>	1	pcs.	680.00	#1	680.00	727.60
225/40R18	LHF DOOR LOWER HINGE <i>3 X SUC</i>	1	pcs.	195.00	#1	195.00	208.65
	Oval Hexagon Socket Head <i>ne</i>	8	pcs.	840.00	#1	6,720.00	7,190.40
	Alloy Wheel Galvano Grey <i>SUC</i>	8	pcs.	800.00	#1	6,400.00	6,848.00
	Rubber Valve <i>ne</i>	1	pcs.	840.00	#1	840.00	898.80
	Pirelli CintuP7 225/40R18 <i>SUC 70%</i>	1	pcs.	840.00	#1	840.00	898.80
	Towing assistance - AWP	1	pcs.		#1		
	LABOUR	8	pcs.		#1		
	SPRAY PAINT	8	pcs.		#1		
	TRANSFER DOOR MECHANISM	1	pcs.		#1		
	R&R FRT LUGGAGE TRIM	1	pcs.		#1		

Quotation valid till 21-12-2020

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/3

Mr
LOW
HAN SIONG
7 VERDE PLACE
Singapore 688617

Document no.
Document date 15-12-2020
Customer no. 5211035173
Customer GST-ID
Dealer 30001
Job order number 2020034525/ 1
Job order date 14-12-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SLG6352R	5G13HZ	07-10-2016	VWVWZZZAUZH057969	Golf 1.4 CLBM 92 TSI D7F	52,906

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	To Align LED Headlight	1	pcs.	100.00	#1	100.00	107.00
	R&R RIM & BALANCE	2	pcs.	50.00	#1	100.00	107.00
	Wheel Alignment	1	pcs.	360.00	#1	360.00	385.20
5G0807217BPGRU	Cover For Bumper Primed <i>de</i>	1	pcs.	1,158.63	#1	1,158.63	1,239.73
5G0805915 9B9	Retainer For Spoiler Sati <i>XSL</i>	1	pcs.	188.11	#1	188.11	201.28
5G0998399 GRU	1 Set Sensor Brackets Pri <i>nee</i>	1	pcs.	21.89	#1	21.89	23.42
5G0919493	Sensor Bracket <i>nee</i>	1	pcs.	14.21	#1	14.21	15.20
5G0919493A	Sensor Bracket <i>nee</i>	2	pcs.	14.21	#1	28.42	30.41
5G0919494	Sensor Bracket <i>nee</i>	1	pcs.	14.21	#1	14.21	15.20
D 180KU2A1	2k-Plastic Adhesive <i>nee</i>	1	pcs.	75.94	#1	75.94	81.26
D 822150A1	Bonding Agent For Plastic <i>nee</i>	1	pcs.	59.40	#1	59.40	63.56
5Q0919297B GRU	Sensor Primed <i>XSL</i>	1	pcs.	172.33	#1	172.33	184.39
5Q0919133 9B9	Seal Ring Satin Black <i>XSL</i>	1	pcs.	1.21	#1	1.21	1.29
5G0807723D	Support Part	1	pcs.	54.69	#1	54.69	58.52
	BUMPER INNER BRACKET LH <i>3cm</i>	1	pcs.				
5G0807049A	Guide Piece	1	pcs.	20.91	#1	20.91	22.37
	BUMPER SIDE BRACKET LH <i>3cm</i>	1	pcs.				
5G0807050A	Guide Piece	1	pcs.	20.91	#1	20.91	22.37
	BUMPER SIDE BRACKET RH <i>3XSL</i>	1	pcs.				
5G0853211E 9B9	Cover Part For Bumper Sat <i>de</i>	1	pcs.	27.86	#1	27.86	29.81
	LHS FOG LAMP GRILLE	1	pcs.				
5G0853665 9B9	Cooling Air Grill Satin B <i>3XSL</i>	1	pcs.	91.45	#1	91.45	97.85
	LHS FOG LAMP GRILLE LOWER TRIM	1	pcs.				
7P6853910A	Clamp <i>nee</i>	2	pcs.	2.80	#1	5.60	5.99
	CLIP	1	pcs.				
5G2941753	Headlamps For Curve Light <i>3cm</i>	1	pcs.	2,091.76	#1	2,091.76	2,238.18
	LH	1	pcs.				
8K0941597E	Ballast For Gas Discharge <i>XSL</i>	1	pcs.	791.96	#1	791.96	847.40
4G0907697F	Power Module For Day Driv <i>short</i>	1	pcs.	392.42	#1	392.42	419.89
3D0941329D	Power Module For Cornerin <i>XSL</i>	1	pcs.	507.12	#1	507.12	542.62
3C0973737	Flat Contact Housing With <i>3cm</i>	1	pcs.	18.43	#1	18.43	19.72
	H/LAMP WIRE HOUSING	1	pcs.				
5G0955453AE	Wash Water Reservoir <i>nee</i>	1	pcs.	135.38	#1	135.38	144.86
7M0919382	Seal Ring <i>nee</i>	1	pcs.	9.86	#1	9.86	10.55
7M0919376	Water Level Switch <i>nee</i>	1	pcs.	27.69	#1	27.69	29.63
3Q0955455	Sealing Cap <i>nee</i>	1	pcs.	12.65	#1	12.65	13.54
443955465	Gasket <i>nee</i>	1	pcs.	1.95	#1	1.95	2.09
431955465A	Gasket <i>nee</i>	1	pcs.	4.70	#1	4.70	5.03
G 052184A2	Windshield Cleaner Concen <i>nee</i>	1	pcs.	15.71	#1	15.71	16.81
1J0955875P	Coupling Piece <i>nee</i>	1	pcs.	17.66	#1	17.66	18.90
1J0955875R	Coupling Piece <i>nee</i>	1	pcs.	17.66	#1	17.66	18.90
5G0821105A	Fender	1	pcs.	615.49	#1	615.49	658.57
	FENDER LH <i>bt</i>	1	pcs.				

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Mr
LOW
HAN SIONG
7 VERDE PLACE
Singapore 688617

Page 3/3
Document no.
Document date 15-12-2020
Customer no. 5211035173
Customer GST-ID
Dealer 30001
Job order number 2020034525/ 1
Job order date 14-12-2020
Service Advisor CHARMAINE KONG

License plate	Model code	First registration	VIN	Model	Mileage
SLG6352R	5G13HZ	07-10-2016	WVWZZZAUZH057969	Golf 1.4 CLBM 92 TSI D7F	52,906

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,320.00	30,259.06	7%	2,210.53	31,579.06	33,789.59
Total	1,320.00	30,259.06		2,210.53	31,579.06	33,789.59

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ASU
Hp 20010068

13 days

18/12/2020 @ 1000

Resy before paint

Supplementary or Omitted List



VEHICLE NUMBER: **SLG6352R**

MODEL **Golf 1.4**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
1				
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
	5G0955965	NOZZLE CYLINDER LH	1	\$129.30		\$129.30
	000979992A	1 Set Of Shrink Fit Sleeve	1	\$64.39		\$64.39
TOTAL:						\$193.69

✓ cra
✓ nec

Total Labour & Parts

\$193.69