## COMFORT DELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\*** 

SHD4422Z **VEHICLE NO** 

**HYUNDAI** 

IONIO G3

MAKE

DATE: 15.12.2020 MVA: CHIANG/NTUC

Amount

MODEL	IONIQ G3	Tuno		Amount
Qty	Parts Description/ Labour	Туре		\$459.40
	DEAR RUMPER X MODALY			\$451.25
1	I CENTRE MOUIDING 本 \ \//\/	ľ	\$55.80	\$111.60
1	DEAD BLIMPER SIDE BRACKET LH /KH /		\$2.20	\$22.00
10	IREAR RUMPER COVER CLIPS / "" ""		<b>7-</b>	\$1,044.25
	300 10175	1		\$208.85
	20.00%	l		\$835.40
	DISCOUNTED TOTAL			
	<b>*</b>			\$50.00
1	REAR BUMPER MAT X C N 10.00%			\$180.00
1	REAR REVERSE SENSOR X / 10.00%			\$212.00
			2	
	Labour Charge		320	\$700.00
	Panel Beating		320 200	\$500.00
	Spray Painting Charge		A(A/X)	\$60.00
	Tuff Kote		/*/  X [	\$60.00
	Check Wiring		40	\$60.00
	Remove/refix Reverse sensor  TOTAL LABOUR			\$1,380.00
				40.407.40
	ESTIMATE TOTAL			<u>\$2,427.40</u>
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2 Days.

put my put.

before a Afrew paint phtos.

before a Second Secon

- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: