



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20014087/Ktd3q2 Date: 14/01/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLJ 1032G	Veh. Inspected	SLZ 8733L	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008373/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	18/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE (A)	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	AGH300033829	Colour	METALLIC BLACK	
Odometer	312485 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	PIRELLI	7 mm	
L/H Front Tyre	235/50 R18	PIRELLI	7 mm	
R/H Rear Tyre	235/50 R18	TOYO	6 mm	
L/H Rear Tyre	235/50 R18	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/12/2020	Inspection Date	18/12/2020	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	