

REF:

## 10 Oct 2016

Veh No: SFA833L Yr Regn: 10 Oct 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: HONDA HRV 1.5 DX CVT C.C 1496

Colour      White      A/C:      Insured / Std / NI / NA

Sp. Reading T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMRU1810GX200370 \*

Gen. Cond: Good / Fair / Poor / Burnt


Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: DUNLOP 215/60R16

R: DUNLOP 215/60R16

	
N/S	O/S

Front Rear

R/Bal.	mm	R/Bal.	mm
--------	----	--------	----

L/Bal.	mm	L/Bal.	mm
--------	----	--------	----

D.O.A.	D.O.I.
--------	--------

Survey held at \_\_\_\_\_

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report

**□ : Final Report**

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$

Tech. Invs (\$)

☐ Weekend (\$

Transportation:

1) Photos

Others

TOTAL