

ASS. REC. BY:

RASHA

REF:

CC4/111 20014/08/Rips3

422F

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKZ 8526Eat Workshop m/s WEARNESof 45, Lenth KEE ROInsured: 111

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 82k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKZ 8526EYr Regn: 2016 / RABType: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: JAGUAR XE 2.0 14P.TDS c.c. 1999Colour Brown

A/C: Insured / Std / NI / NA

Sp. Reading 09229

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SADA B4AG36A905078Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orModi: Nil / ☒ SRim / STD A/Rim orTyre Size: F: 225/50R17

R: _____

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 17/12/2020D.O.I. 18/12/2020Survey held at WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair / Int - 14k

Date/Time, File Pass to?



: Prell. Report



: Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC

Owner ID: 422F

Vehicle No.: SKZ8526E

Vehicle to be Exported: No

Intended Deregistration Date: 20 Dec 2020

Vehicle Make: JAGUAR

Vehicle Model: XE 2.0 I4P TSS

Primary Colour: Beige

Manufacturing Year: 2015

Engine No.: 015082054807204PT

Chassis No.: SAJAB4AG3GA905078

Maximum Power Output: 147.0 kW (197 bhp)

Open Market Value: \$43,598.00

Original Registration Date: 04 Feb 2016

First Registration Date: 04 Feb 2016

Transfer Count: 0

Actual ARF Paid: \$53,038.00

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Feb 2026

PARF Rebate Amount: \$39,778.00

COE Expiry Date: 03 Feb 2026

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$57,501.00

COE Rebate Amount: \$28,170.00

Total Rebate Amount: \$67,948.00

The information contained herein is correct as at 20 Dec 2020

OK

Beige

mart.com/used_cars/info.php?ID=939415&DL=1000

► Jaguar XE Diesel 2.0A Prestige

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$82,000	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation ⓘ	\$11,530 /yr View models with similar depre	Reg Date	17-Feb-2016 (5yrs 1mth 27days COE left)
Mileage	91,000 km (18.8k /yr)	Manufactured ⓘ	2015
Road Tax ⓘ	\$1,812 /yr	Transmission	Auto
Dereg Value ⓘ	\$62,152 as of today (change)	OMV ⓘ	\$45,009
COE ⓘ	\$57,501	ARF ⓘ	\$45,013
Engine Cap	1,999 cc	Power	132.0 kW (177 bhp)
Curb Weight ⓘ	1,574 kg	No. of Owners ⓘ	1
Type of Vehicle	Luxury Sedan		

Features

2.0 Litre Inline 4 Turbocharged Diesel Producing 177Bhp, 430NM Torque. 8 Speed Auto Transmission, 0-100Km/H In 7.8s. Rear Wheel Drive. View specs of the Jaguar XE (2015)

Accessories

Multi-Function Steering Wheel, LED DRL, Keyless Entry/Start/Stop, Reverse Camera, Electric Tailgate. New Iroad X5 Camera With Memory Card

