ASSIGNED BY: [illegible] TH

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s Pan Euro Bike

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBR 6251J 1st Regn: 03 Sep 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: SYM Jet 14 200 c.c 169

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: – T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: LXMXCA501KXA20725

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 100/90-14

R: 110/80-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CST

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	mm	L/Bal.	mm
D.O.A.		D.O.I.	16-12-20

Survey held at W/S 11:30

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Technical ($)

☐ : Assist Engr

Survey Fee:

Transportation: $ + RS. SI

Photos

Other

Total