

# PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462  
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg  
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT  
INDIA INT'L INS PTE LTD

DATE: 11.12.2020

## ESTIMATED COST OF REPAIRS TO SYM JET-14 200

ENGINE NO :

CHASSIS NO :

VEHICLE NO : FBR 6251J

ACCIDENT ON : 06.12.2020

INSURED : SIE LIEN

|      |                                             |
|------|---------------------------------------------|
| 1 PC | RH MIRROR / Cut                             |
| 1 PC | RH BAR END, MATT BLACK / Cut                |
| 1 PC | RH BRAKE LEVER / Cut                        |
| 1 PC | METER DASH, MATT / Cut                      |
| 1 PC | REAR SHIELD, MATT / CAA                     |
| 1 PC | FRONT COWLING, RH, WHITE / Dis              |
| 1 PC | RH FRONT SIGNAL / CAA                       |
| 1 PC | HEADLAMP ASSY / Cut                         |
| 1 PC | FRONT LOWER PANEL, MATT BLACK / Dis         |
| 1 PC | FRONT MUDGUARD, BLACK / CAA                 |
| 1 PC | RH FRONT FORK ASSY / Cut                    |
| 1 PC | RUBBER BUNG, FRONT WHEEL AXLE, RH R / Cut   |
| 1 PC | RH FLOORBOARD LOWER PANEL, TEXTURED / } Mis |
| 1 PC | RB FLOORBOARD LOWER PANEL, MATT GREY / }    |
| 1 PC | FLOORBOARD BRACKET, RH / BT                 |
| 1 PC | BOTTOM BELLYPAN, MATT / Cut                 |
| 1 PC | FLOORBOARD, MATT / CAA                      |
| 1 PC | EXHAUST GUARD, MATT PLASTIC / Cut           |
| 1 PC | EXHAUST MUFFLER / BT                        |

TOTAL

\$ -

LESS 10%

\$ -

SUB TOTAL

\$ -

### NETT ITEMS:

|       |                                         |
|-------|-----------------------------------------|
| 1 SET | DECAL, "200", FRONT COWLING / AC        |
| 1 SET | EMBLEM, "JET 14", RH REAR FAIRING / Mis |
| 1 SET | REAR TOP BOX, GIVI / Cut                |
|       | LABOUR CHARGE                           |

### REMARKS:

Kindly send a surveyor down for a 3rd Party claim against your insured SH 6285M.

Thank You.

Kin Wah: 9731-7133

SUB TOTAL

\$ -

ADD 7% GST

\$ -

GRAND TOTAL

\$ -

2 Days.  
part by part  
After repair photos.  
Limo Ricap.  
16/12/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: