

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping

Date: 10.12.2020

Time: 13:48:02

Page: 1

~~Great Eastern~~
(P/P)

12 IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438275
REGN NO : SH 9775X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 26.06.2019
DATE/TIME IN : 10.12.2020 09:55
ACCIDENT DATE : 09.12.2020

LKK-Taufikh

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 FNPS	NO PLATE(S)W/TRIM COVER	1 N	55.00	55.00	/CRK
0002 04-01-0104-2282-G	REAR BUMPER	1	459.40 20.00	367.52	/DEF
0003 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25 20.00	361.00	? /DEF
0004 04-01-0104-2370-G	REAR BUMPER FOGLAMP	1	201.50 20.00	161.20	X SJC
0005 04-01-0104-2288-G	REAR BUMPER BEAM	1	394.80 20.00	315.84	X NN
0006 04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00 20.00	124.00	X NN
0007 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00 20.00	17.60	/NEC
0008 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	180.00	X /DEF
0009 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00	50.00	/NEC

SUB-TOTAL : 1,632.16

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	/NEC
0001 20-05	Rear Bumper Adv.Sticker	50.00	/NEC

China Taiping

COMFORTDELGRO ENGINEERING PTE LTD

Date: 10.12.2020

Time: 13:48:02

REPAIR ESTIMATE

~~Great Eastern~~
CP(P)

Page: 2

PS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305438275
REGN NO : SH 9775X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 26.06.2019
DATE/TIME IN : 10.12.2020 09:55
ACCIDENT DATE : 09.12.2020

LKK - Taufik

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 PB PANEL BEATING

~~350.00~~ 320

0003 SP SPRAYPAINT CHARGE

~~250.00~~ 200

0004 L R/I REVERSE SENSOR

~~120.00~~ 30

SUB-TOTAL : 970.00

TOTAL : 2,602.16


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NA2 LKIC

11/12/2020 1200

PIP

2 DAYS

CHECK ITEM PHOTOS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: