



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20014164/Avf3n2 Date: 15/06/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 6587A	Veh. Inspected	SMV 7170B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008405/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	21/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVWZZZAUZGW164420	Colour	BLUE	
Odometer	54764 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	PIRELLI	6 mm	
L/H Front Tyre	225/40 R18	PIRELLI	6 mm	
R/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
L/H Rear Tyre	225/40 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/12/2020	Inspection Date	23/12/2020	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	