KEF: SCTI

ASSIGNMENT

rom: Date:	Veh No: SDZ 8118 H Yr Regn: 12/08/2015
Estimated Cost;	Type: M.Can / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyotylexy E5250 c.c 249
at Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 31615 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JTHBJ14400208-3110
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Indider Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S(Rim / STD A/Rim or
	Tyre Size: F: 215 /55/RI7
(Policy Condition)	R: 215 / 55/R17
Remark: The veh had commenced its N/S O/S	-
repair at the time of inspection.	TOYO (YOK) or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. 11/12/2020 D.O.I. #21/12/2020
Lum Sum: % 3 Val.: Yes or No	Survey held at Auto Inssure.
CA / REV / REP. / 24 HRS	Des. of Damages (Frt) / (Rea) / O/S / N/S / U/C / Rooftop or
Vehicle: IN / O	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV: 87,000	
PV: 56,712	1
NV: 30,288	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add	Fee: : Site Insp (\$)s+RSSI
	: Interview (\$) Photos
Rep rof Formai:	:Tech. Invs (\$) Others
Lump Sum / LB.A: (%)	: Weet and (%)
·	TOTAL

SA1C20CB0002-01 / Auto Insure Pte Ltd [608586] ENTRY DATE & TIME: 11/12/2020 17:26 (SGT) SUBMITTED BY: LIM WEI LING VERSION: 2 (11/12/2020 17:50 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

opolicy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

11/12/2020 17:26 (SGT) 11/12/2020 12:00 (SGT) Dairy Farm Rd, Singapore AT JUNCTION OF DAIRY FARM ROAD Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SDZ8118H

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

No

JASHANDEEP SINGH

SXXXX784D

Singhjashan07@gmail.com

(Phone) +65-91052752

+65-91052752

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category

Lexus

Es250

Private use

No - Claiming third party

Private car

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage

Fleet Policy

Policy Number

Cover Note Number

DRIVER

Name of Driver

NRIC No

Date Of Birth

Occupation

Accident report SA1C20CB0002

Direct Asia

Comprehensive

No

MT/00803100

JASHANDEEP SINGH SXXXX784D 08/11/1986 Indoor

Page 1 of 34

Oate Of Driving Pass Driving experience

Gender

Mobile Number Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

12/12/2005 15 YEARS

Male

(Phone) +65-91052752

+65-91052752

Singhjashan07@gmail.com

BLK 803C KEAT HONG CLOSE #10-12

683803

Yes

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Chain Collision

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Nο Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes 3 Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) Yes

PASSENGER 1

Name Gender **PASSENGER**

Female

PASSENGER 2

Name Gender **PASSENGER**

Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

soliciting/offering accident claims assistance?

No

No

CIRCUMSTANCES OF ACCIDENT

ON 11/12/2020 AT 1200 HRS, I WAS AT THE JUNCTION OF DAIRY FARM RD WAITING FOR THE LIGHTS TO TURN GREEN. I WAS IN THE 2ND LANE WHEN I FELT A HARD IMPACT FROM MY REAR AND REALISED VEHICLE B HAD COLLIDED ONTO MY VEHICLE. I WISH TO STATE THAT IT WAS A 3 CAR CHAIN COLLISION, VEHICLE B HAD COLLIDED ONTO MY VEHICLE AND AS THE IMPACT WAS VERY HARD IT CAUSED MY CAR TO SURGED FORWARD AND HIT ONTO VEHICLE C. IN MY CAR WAS MY WIFE, WHO IS PREGNANT, MY 16 MONTH OLD DAUGHTER AT THE BACK & MYSELF IN THE DRIVER SEAT.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes

No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

le Registration Number

SME951A

hicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category Private car

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SME7443D

Vehicle Manufacturer

Vehicle Model

Vehicle Variant
Vehicle Colour

Vehicle Category Private car

Name of Driver

Contact Number -

Address -

Address complement -

Postcode - Insurance Company Name -

Nature Of Damage -

Details of property damaged in accident -

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This form most be completed by the Policyholder and/or the Authorised Driver
- information provided must be an invitabiliand accurate as possible. Any will his necessanishing or withholding of material facts may allow inversors companies to repudiate policy liability.
- 4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation
- The report will be foreer died by the insurers of the GIX Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and this copies of this report will for a fee be made available upon application by
- By the Indement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, series and romsem that

- (5) My invursi, my workshop and the General Invariance Association of Singapore (*GIA*) may/are permitted to collect, use, esticate and/or process my personal data/personal information as to sur in this (form) and any other personal information provided by my or possessore the my invarie (collective) the "Personal Information" and disclose and craser such Personal Information and accident fail invarient such as the market which is involved in this accident fail invarient such as where the collection works are done to the processor as the processor as the processor as the processor as the processor and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

- (v) administering my claims (including the mailing of correspondence, statements, invalices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- ell insurer(s) who have insured vehicle(s) involved in this accident and the Insurer's Jawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (C) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (n) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, low enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature (if driver is not the policynolder) Date 8-Time:

SKETCH PLAN	Dainy Farm	Kd
	8 100	A > S028118H B - SME ASIA C - SME 74430
DESCRIBE CIRCUMSTAN	CES OF THE ACCIDENT	And I am to the second
Amilian Lighte 1 Ligh	al with the	kd northy for The Was in The Ind land Mall from My rear had collided onto State that IT was to remick & had a The impact I way car to surged velocity.
		>
Solver	rticulars are true in every respect.	M
Policyholder's Signature Date & Time:	Driver's Signature (if driver is not the policyhologr) Date & Time	Reporting Centre Personnel's Signature Name: NRIC/FIX No.:

Auto Insure Pte. Ltd 6 Marsiling Lane 739145

Insurer Reference: M1237 Repairer Reference: SDZ8118H

Date calculated: 16/12/2020 9:42 AM



Registration: SDZ8118H

Printed: 16/12/2020 9:42 AM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

Sam Goh M1237

Currency:

Date of Incident:

SGD 11/12/20

Estimated Repair Time:

Actual Repair Days:

Hire Car Start: Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

LEXUS

Model:

ES (V6)

Sub Model:

250

Model Sheet Number:

24 23 30 SDZ8118H

Registration: VIN number:

Odometer:

Model Specs TWO COAT METALLIC

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All

Underbody



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

Audatex System Using Manufacturer Times

Page 1 of 4

PRINT DATE 16/12/2020

Code	Description		WU	Price SGD
B020	RENEW FRONT BUMPER		23.0	96.60
	INCLUDES: R + R FRONT BUMPER, RADIATOR			
NO NUMBER	GRILLE AND NECESSARY ATTACHED PARTS		4.0	4.20
B070	R + R FRONT BUMPER DAMPER RENEW BONNET		1.0 6.0	4.20 25.20
5070	INCLUDES: ASS ATTACHED PARTS AND IF NECE		0.0	25.20
	RENEW			
B290	RENEW END PANEL		38.0	159.60
	(BUMPER REMOVED)			
	INCLUDES: R + R BOOT FLOOR CARPET AND			
	ALL TRIMS IN THE REPAIR SECTION			
B360	RENEW BOOT LID		12.0	50.40
	INCLUDES: R + R BOOT LID,			
41.44.	CONVERT ATTACHED PARTS			
811201)	R + R L/NUMBER PLATE LAMP		2.0	8.40
811201)	R + R R/NUMBER PLATE LAMP		2.0	8.40
NO NUMBER NO NUMBER	R + R L/R BUMPER BRACKET		2.0	8.40
B410	R + R R/R BUMPER BRACKET R + R REAR BUMPER CARRIER		2.0 1.0	8.40 4.20
B420	RENEW REAR BUMPER		11.0	46.20
D420	INCLUDES: BUMPER AND ALL		11.0	40.20
	REQUIRED ATTACHED PARTS R + R			
B407	R + R L/OUTER REAR LAMP		2.0	8.40
B407	R + R R/OUTER REAR LAMP		2.0	8.40
3901	REAR FLOOR PANEL REPAIR ?		30.0*	126.00
	* Tull lan			
	Labour Cost * Tail lamp pane 20.0:		WU	
	Panel / Mechanical Labour ' '	13.40	134.0	562.80
	Total of Labour			562.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	26.0
	END PANEL NEW PART PAINTING	22.0
	BOOTLID NEW PART PAINTING	19.0
	FRONT BUMPER NEW PART PAINT K1R	13.0
	REAR COVER BUMPER NEW PART PAINT K1R	14.0
	REAR FLOOR PANEL SURFACE PAINT	12.0

Paint Material Per Part

Code Description	Price SGD
0471 BONNET NEW PART PAINTING 2711 END PANEL NEW PART PAINTING 2931 BOOTLID NEW PART PAINTING 0283 FRONT BUMPER NEW PART PAINT K1R 2583 REAR COVER BUMPER NEW PART PAINT K1R 3901 REAR FLOOR PANEL SURFACE PAINT	86.17 28.05 55.73 61.50 70.85 40.84

Labour Cost - Paint Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic		2.10 0.50	106.0 21.0 5.0	88.20 21.00
Material Cost - Paint New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Material-constant Plastic Total	10 WU/h	13.20	132.0	554.40 Price SGD 169.95 132.35 40.84 18.10 9.00 370.24

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
	•			
0471	BONNET WWW		Original	850.00
2931	BOOTLID / pr	64401 33650	Original	420.00
2979	BOOTLID TRIM 🗴	76801 33450	Original	165.00
2711		2Þ 58307 33171	Original	275.00
4985	END PANEL TRIM /	CMU 58387 33150C0	Original	165.00
0283	FRONT BUMPER 💉	Chu 52119 3T918	Original	375.00
0344	FRONT BUMPER ? DAMPING	52611 33220	Original	80.00
0410	GRILLE C	W 53111 33440	Original	385.00
0431	GRILLE BADGE		Original	155.00
0420	GRILLE MOULDING		Original	145.00
2619	2 L/R INN BUMPER BR		Original	75.00
2609	2 L/R UPP BUMPER BR		Original	50.00
3015	NPC MANUFACTURER SAI	DGE 75447 33180		0.00
2620	7 R/R INN BUMPER BR	KT 52155 33010	Original	85.00
2610	7 R/R UPP BUMPER BR		Original	70.00
3013	NA REAR BADGE	90975 02142	Original	50.00
2625	REAR BUMPER DAME	PER 52615 33140	Original	70.00
2640	77 REAR BUMPER SUPP		Original	210.00
	REAR COVER BUMPE		Original	475.00
	REAR DECAL STRIPE			0.00
	UPPER AIR GUIDE	53295 33080	Original	135.00
	NEC VERSION BADGE	75442 33400	3	0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Part	ts Subtotal			4,235.00
u: Used parts	Total			4,235.00

Extras

Code	Description	Price SGD
1000 1001	FRONT CAR PLATE / CMU REAR CAR PLATE / SCM. Total Extras	60.00* 60.00* 120.00

	_		
Desc	rip	tic	n

Price SGD

l a Ludation		
al Calculation	SGD	SGD
Parts Total Parts	4,235.00	4,235.00
Labour Time Base 10 WU/h Total 134.0 WU X 42.00 SGD/h Total of Labour	562.80	562.80
Total Of Extras	¥.	120.00
Paint Work Time Base 10 WU/h Labour Cost 132.0 WU X 42.00 SGD/h Material Cost Total Paint Including Material	554.40 370.24	924.64
Repair Cost Excludes GST		5,842.44
GST (+7.00%)		408.97
Repair Cost Included GST		6,251.41

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	784D
Vehicle Details	
Vehicle No.:	SDZ8118H
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Dec 2020
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES250 AUTO
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2ARF057886
Chassis No.:	JTHBJ1GG002083110
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$34,805.00
Original Registration Date:	12 Aug 2015
First Registration Date:	12 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$40,727.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2025
PARF Rebate Amount:	\$28,508.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,789.00
COE Rebate Amount:	\$28,204.00
Total Rebate Amount:	\$56,712.00

The information contained herein is correct as at 21 Dec 2020

