

ASS. REC. BY:

REF:

CS/CTI20014171/Avf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SLU 27X**Policy No. **DMPCSNW00156262000**

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SMN8760J** Yr Regn: **2019 / Augnt.**Type: **M.Car** / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Vezel** c.c. **1496**Colour: **Grey** A/C: Insured / Std / NI / NASp. Reading: **19423** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **Ru11320736**Gen. Cond: **Good** / Fair / Poor / BurntSteering: **Inorder** / Jammed / Leaked / Burnt orBrake: **Inorder** / Jammed / Leaked / Burnt orModi: Nil / **S/Rim** / STD A/Rim orTyre Size: F: **215/60R16**R: **215/60R16**BS: **DUN** / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **17/12/20** D.O.I. **21/12/20**Survey held at **N51**Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China
	MV :
	PV :
	Nett :
4/4/21	Adrian confirmed LS \$6500 (Red 3732.92, 36%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) **5/4/21-Typist**Days Of Repair: **6**Resurvey No. of Trip: **1**

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format: **Merimen**Lump Sum / I.B.J. @ **LS \$6500**

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/12/2020 10:17 (SGT)
Date of Accident	17/12/2020 19:50 (SGT)
Exact Location of Accident	Near PIE, Singapore
Additional Location Information	PIE TOWARDS TUAS (BEFORE BALESTIER RD EXIT)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN8760J
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LU YI
NRIC No	SXXXX833Z
Email Address	LUYI@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97871501
Alternative Phone No	(Home) +65-97871501

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5112277867-01 (DRIVO CLASSIC)
Cover Note Number	-

DRIVER

Name of Driver	LU YI
NRIC No	SXXXX833Z
Date Of Birth	14/09/1978
Occupation	Indoor

Date Of Driving Pass	18/02/2008
Driving experience	12 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97871501
Alt. Phone Number	(Home) +65-97871501
Email Address	LUYI@HOTMAIL.COM
Address	APT BLK 19 GHIM MOH ROAD #14-245
Address complement	-
Postcode	270019
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	FATHER
Gender	Male

PASSENGER 2

Name	MOTHER
Gender	Female

PASSENGER 3

Name	WIFE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT ATTACH

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU27X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMC4549M
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LU YI
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMN8760J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

Name of injured person	FATHER
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SMN8760J
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	No

INJURED 3

Name of injured person	MOTHER
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-



Injuries Sustained -
Injured person in which vehicle? SMN8760J
Were seat belts worn? -
Was this injured conveyed to hospital by ambulance? No

INJURED 4

Name of injured person WIFE
Address -
Address Complement -
Post Code -
Approximate Age Years Old -
Injuries Sustained -
Injured person in which vehicle? SMN8760J
Were seat belts worn? -
Was this injured conveyed to hospital by ambulance? No


SKETCH PLAN

P16 toward Tuss before Bolester Road exit.

Vehicle A
- SLU 27 X

Vehicle B
- SMC 4549 M

Vehicle C
- SMN 8760 J



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along P16 toward Tuss direction, I was on the extreme right lane.

While driving straight ahead, due to the vehicle in front brake to complete stop, and so I too applied brake to complete stop, which suddenly after a few seconds, I felt a great impact from the rear of my vehicle, the impact causes me, pushed forward and hit onto the vehicle in front of me.

Wighted from my vehicle and realized it was a vehicle with licence plate (SMC 4549 M) that collided to the rear of my vehicle and causing a great impact that pushed me forward to hit onto the vehicle in front.

The whole accident footage was captured by my in-car camera.

Vehicle A - SLU 27 X

Vehicle B - SMC 4549 M

Vehicle C - SMN 8760 J

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Report Centre Personnel's Signature
Name:
NRIC/FIN No: