

ASS. REC. BY:

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKA2226S Yr Regn: 2019, Sept.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios c.c. 1496Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 26003 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR2B23F310189\*251Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15R: 185/60 R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 16/12/20Survey held at Success UnitedDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP AIG</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / LBJ: C \_\_\_\_\_

Add Fee:

☐

Site Insp (\$ \_\_\_\_\_)

☐

Interview (\$ \_\_\_\_\_)

☐

Tech. Invs (\$ \_\_\_\_\_)

☐

Weekend (\$ \_\_\_\_\_)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	388Z
<b>Vehicle Details</b>	
Vehicle No.:	SKA2226S
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Nov 2020
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Brown
Manufacturing Year:	2019
Engine No.:	2NR5393167
Chassis No.:	MR2B23F3101189251
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,787.00
Original Registration Date:	30 Sep 2019
First Registration Date:	30 Sep 2019
Transfer Count:	0
Actual ARF Paid:	\$13,787.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2029
PARF Rebate Amount:	\$10,340.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Sep 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,783.00
COE Rebate Amount:	\$28,233.00
<b>Total Rebate Amount:</b>	<b>\$38,573.00</b>

The information contained herein is correct as at 11 Nov 2020

OK