

CS3/A/G 20014188/Gvf3

ASSIGNMENT

Estimated Cost:

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s Prospin Motorsports

Insured:

Policy No:

Claims No:

Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

JAC Accident Report:

GIA / PR Seen:

First Repairs:

Sum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Date / Time Action / Instruction

No GIA provide

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

24/12/20-Typist

DAR

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Photo (\$☐ Other (\$

Survey Fee:

Transportation:

1. 1st & 2nd

2. Photo

3. Other

Veh No: FBP3620H Regn: 2019

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

w/s

5pm