



Service Request Details

Claim
SOM02Z84

Reference
None 

Loss Date
December 19, 2020

Report Date
Dec 21, 2020 2:38:28 PM

Request Date
December 21, 2020

Due Date
December 21, 2021

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pre-Repair Survey

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Make
TPVD

Model
TOYOTA

Service Address

, , ,

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg
Additional Instructions

- 3
- Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	 REPLY FROM TP.msg
TYPE	Letters and Correspondence
SUB-TYPE	Solicitor / Advocate
AUTHOR	KUMAR Shailendra

DATE UPLOADED December 21. 2020

