

ASS. REC. BY:

Steve

REF:

A16

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLZ 3608Z

Yr Regn:

30/4/18

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage

c.c.

1193

Colour:

Silver

A/C:

Insured / Std / NI / N

Sp. Reading

52685

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

MMBSTA13AJH001935

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

185/55R15

R:

11

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/12/20

D.O.I.

21/12/20

Survey held at

Cycle & Carriage

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Rear RH

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-52 K

File/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

File/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp

(\$

☐

: Interview

(\$

☐

: Tech. Inve

(\$

☐

: Weekend

(\$

Top Forms:

ump Sum / L.B. / C.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Kok Yik Kuen
	Reg No/Reg Date	SLZ3608Z / 30/04/201
	Date In/Mileage	21/12/2020/ 0
	Chassis No	MMBSTA13AJH001935
	Engine No	3A92UGT5902
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2020/ 13:41	QUK	282 / Kevin Leong	61001			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT, REAR RH TAIL LAMP PANEL & AFFECTED AREA REPAIR ON REAR RH FENDER					450x 3			2700.00 1350
E PNT98000 PAINT WORK ON REAR BUMPER, BOOT, REAR RH FENDER, REAR RH TAIL LAMP PANEL, BODY KIT & END PANEL					350x 5			2100.00 1750
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								120.00
E PNT88000 REMOVE & INSTALL REAR BOTO COMPARTMENT FOR FACILITATE REPAIR								(phrb) 120.00
E PNT88000 TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL								120.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA								80.00
M SUNDRY PERFORM RUST PREVENTION								40 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY TO SUPPLY C & C EMBLEM								40.00
M SUNDRY SUNDRIES								20 50.00
M UNPAINTED BODYKITS					1.00	1643.00	20.00	1314.40
M PANEL,RR COMB LAMP HSG,RH					1.00	60.00	23.00	46.20
M LAMP ASSY,COMB,RR RH					1.00	335.00	23.00	257.95
M FACE,RR BUMPER					1.00	748.00	23.00	575.96
M BRACKET,RR BUMPER,RH					1.00	28.00	23.00	21.56
M PANEL,RR END					1.00	425.00	23.00	327.25
M PANEL,TRUNK LID					1.00	791.00	23.00	609.07
M WEATHERSTRIP,TRUNK LID					1.00	157.00	23.00	120.89

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Kok Yik Kuen Reg No/Reg Date SLZ3608Z / 30/04/201 Date In/Mileage 21/12/2020/ 0 Chassis No MMBSTA13AJH001935 Engine No 3A92UGT5902 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/12/2020/ 13:41	QUK	282 / Kevin Leong	61001			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE, TRUNK LID, LH	X			1.00	203.00	23.00	156.31
M	HINGE, TRUNK LID, RH	X			1.00	203.00	23.00	156.31
M	STRIKER, TRUNK LID LATCH	X			1.00	20.00	23.00	15.40
M	LATCH, TRUNK LID	X			1.00	218.00	23.00	167.86
M	GARNISH, RR END PANEL	X			1.00	336.00	23.00	258.72
M	MARK, THREE-DIA	APC			1.00	69.00	23.00	53.13
M	MARK, ATTRAGE	APC			1.00	21.00	23.00	16.17
M	TRIM, RR END	+			1.00	66.00	23.00	50.82
M	BOARD, TRUNK ROOM FLOOR	X			1.00	195.00	23.00	150.15

Estimate

Steve (LKK) QD - NM Authn
21/12/20, 2:30pm EXPRESS - ?
P/P
My Bel spy
7 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Confirm & accepted by
* Supplementary item(s) must be resurveyed and
final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7% GST on **9858.15** **9,858.15**
690.07
Total Payable 10,548.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

21/12/2020 14:09 (SGT)
20/12/2020 14:15 (SGT)
Jurong West Street 64 & Boon Lay Way, Singapore
SLIP RD OF JURONG WEST ST 64 & BOON LAY WAY
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLZ3608Z

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No
KOK YIK KUEN
SXXXX179F
YKKOK@HOTMAIL.COM
(Phone) +65-93841505
+65-93841505

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category

Mitsubishi
Attrage
-
-
Yes
Private car

INSURANCE COMPANY

Name of Insurance Company
Type of Coverage
Fleet Policy
Policy Number
Cover Note Number

AIG
Comprehensive
No
1800043247
-

DRIVER

Name of Driver
NRIC No
Date Of Birth
Occupation

KOK YIK KUEN
SXXXX179F
17/05/1971
Indoor

Date Of Driving Pass	08/04/2009
Driving experience	11 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93841505
Alt. Phone Number	+65-93841505
Email Address	YKKOK@HOTMAIL.COM
Address	BLK 133 LORONG AH SOO #06-434
Address complement	-
Postcode	530133
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number	SHA6944L
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Blue
Vehicle Category	Taxi
Name of Driver	CHUA CHWEE HAI
Contact Number	(Phone) +65-91392802
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-

Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 21/12/2020

1045

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Sunday 20/12/2020, at about 2.15pm, I was driving along Jurong West St 64 and reached the T-junction where turning into Boon Lay Way. Slowing to the left and stop gracefully to allow vehicles on the main road (Boon Lay Way) to clear before I proceed. However, at this very moment, a taxi from behind failed to stop and knocked into the rear of my car. The taxi is of Hyundai model, registration number SIA 694VL.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/12/2020

1045

STAFF ID: 1045

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KOK YIK KUEN
 Period of Insurance : 30 Apr 2020 To 29 Apr 2021
 Engine No. : 3A92UGT5902
 Chassis No. : MMBSTA13AJH001935

Vehicle No. : ST Z36087
 Policy No. : 1800043247-01
 Endorsement No. :
 Issued Date : 03 Apr 2020

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT
 Engine Capacity/Tonnage : 1,193.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARE : Yes

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
 Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019 are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KOK YIK KUEN - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 208 Pandan Gardens Singapore 609339 65684501
 2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
 3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
 4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620207

C&CMICP2 - KERENY

239 ALEXANDRA ROAD
 SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

AIGSGMOBILEAPP