



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 21/12/20
LKK - STEVE

VEHICLE NO : SMW 2051P

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 61000

Material	:	\$	<u>10,034.64</u>
Labour	:	\$	<u>8,255.00</u>
Sub-Total	:	\$	<u>18,289.64</u>
Less 2% Disc	:	\$	<u>-</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>17,989.64</u>
GST 7%	:	\$	<u>1,259.27</u>
Grand Total	:	\$	<u>19,248.91</u>
Finalise By/Date : <u>Larry on 15/01/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 15 WORKING DAYS + 8 days (3 wk. ends)
2 p.H.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWEE Reg No/Reg Date SMW2051P / 09/11/2020 Date In/Mileage 21/12/2020/ 1722 Chassis/Package MMBSTA13AMH00061E /FS5P Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK
21/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 16:56	BLC	884 / Lauro Songcuan	61000

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, FRONT FENDER RH, FRONT SUPPORT PANEL, FRT DOOR RH, REAR DOOR RH, SIDE SILL RH, REPAIR REAR FENDER RH, REAR BUMPER				3600.00 ✓
E PNT88000 REMOVE & INSTALL AIRCON CONDENSER AND RADIATOR				100.00 ✓
A 54900099 VACUUM & TOP UP AIRCON GAS				80.00 ✓
A 54900099 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				120.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER, FRONT FENDER RH, FRONT SUPPORT PANEL, FRONT DOOR RH, REAR DOOR RH, SIDE SILL RH, REAR FENDER RH, REAR BUMPER				2800.00 ✓
E PNT88000 REMOVE & INSTALL FRONT DOOR TRIMS AND GLASS				160.00 ✓
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS AND GLASS				160.00 ✓
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00 ✓
A 54900099 RENEW FRONT UNDER CARRIAGE				450.00 ✓
M SUNDRIES SUNDRIES				20.00 ✓
S TYRESALES2 SUPPLY FRONT RIGHT TYRE				360.00 ✓
S SPECIALISTJOB SUPPLY LABOUR FOR SPORT RIM INSTALLATION WITH VALVE SUPPLY D/N NO:313430				30.00 ✓
A 55900099 RENEW ACCIDENT DAMAGED PARTS AIR CON COMPRESSOR UNIT, → <i>supp.</i> AIR SUCTION PIPE & BELTING				225.00 X
X EXC				-300.00



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWEE Reg No/Reg Date SMW2051P / 09/11/2020 Date In/Mileage 21/12/2020/ 1722 Chassis/Package MMBSTA13AMH00061E /FS5P Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK
21/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 16:56	BLC	884 / Lauro Songcuan	61000

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
EXCESS FOR OWN DAMAGE CLAIM				
X FACE,FR BUMPER ✓	1.00	703.00	23.00	541.31 ✓
X GRILLE,FR UNDER ✓	1.00	90.00	23.00	69.30 ✓
X BRACKET,FR BUMPER SIDE,RH ✓	1.00	8.00	23.00	6.16 ✓
X GARNISH,FR BUMPER,RH ✓	1.00	44.00	23.00	33.88 ✓
X AIR DAM,SIDE,FR RH ✓	1.00	19.00	23.00	14.63 ✓
X GRILLE ASSY,RADIATOR ✓	1.00	597.00	23.00	459.69 ✓
X MARK,THREE-DIA ✓	1.00	53.00	23.00	40.81 ✓
X COVER,FR BUMPER ✓	1.00	12.00	23.00	9.24 ✓
X COVER,FR BUMPER GRILLE ✓	1.00	157.00	23.00	120.89 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	168.00	23.00	129.36 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	120.00	23.00	92.40 ✓
X FENDER,FR RH ✓	1.00	428.00	23.00	329.56 ✓
X SHIELD,FR WHEELHOUSE,RH ✓	1.00	98.00	23.00	75.46 ✓
X PANEL ASSY,FR END ✓	1.00	918.00	23.00	706.86 ✓
X PANEL ASSY,FR DOOR,RH ✓	1.00	996.00	23.00	766.92 ✓
X PANEL ASSY,RR DOOR,RH ✓	1.00	831.00	23.00	639.87 ✓
X AIR DAM,SIDE,RH ✓	1.00	189.00	23.00	145.53 ✓
X TAPE,FR DOOR SASH,RH ✓	1.00	29.00	23.00	22.33 ✓
X TAPE,RR DOOR SASH,RH ✓	1.00	29.00	23.00	22.33 ✓
X MIRROR ASSY,DOOR,RH ✓	1.00	638.00	23.00	491.26 ✓
X HEADLAMP ASSY,RH ✓	1.00	1697.00	23.00	1306.69 ✓
X TANK,WINDSHIELD WASHER ✓	1.00	74.00	23.00	56.98 ✓
X WHEEL,DISC ✓	1.00	598.00	23.00	460.46 ✓
X ARM ASSY,FR SUSP,LWR RH ?	1.00	278.00	23.00	214.06 ✓?
X CROSSMEMBER,FR AXLE,NO.1 ?	1.00	864.00	23.00	665.28 ✓?
X GEAR & LINK ASSY,STEERING ✓	1.00	1444.00	23.00	1111.88 ✓
X END ASSY,TIE ROD ✓	1.00	52.00	23.00	40.04 ✓
X HOSE,A/C COMPR SUCTION	1.00	231.00	23.00	177.87 X
X BELT,ALTERNATOR & OTHERS	1.00	79.00	23.00	60.83 X
X PANEL,AIR GUIDE,RH	1.00	14.00	23.00	10.78 X
X COMPR&CLUTCH ASSY,A/C	1.00	1574.00	23.00	1211.98 X
Z TEXT				

supp.

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /ANDREW YAP MING HWEE Reg No/Reg Date SMW2051P / 09/11/2020 Date In/Mileage 21/12/2020/ 1722 Chassis/Package MMBSTA13AMH000618 /FS5P Engine No 3A92UJP3584 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK
21/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 16:56	BLC	884 / Lauro Songcuan	61000

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
OD CLAIM - AIG DOA: 19/12/2020 SURVEY: STEVE (LKK) 21/12/2020 15 DAYS				
Pro Forma				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	10,034.64	Nett	17,989.64
Labour	7,845.00	7% GST on	17989.64
Standard Menu	0.00		1259.27
Specialist Job	390.00		
Diagnostics Job	0.00	Total Payable	19,248.91
Sundry/Others	-280.00		
Total(w/o GST)	17,989.64		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMW 2051 P

<u>Materials</u>		<u>Cost \$</u>
1	Hose, A/C Compr Suction	231.00
2	Belt, Alternator & Others	79.00
3	Panel, Air Guide, RH	14.00
4	Compr & Clutch Assy, A/C	1,574.00
		<u>1,898.00</u>
23% Discount		<u>436.54</u>
		<u>1,461.46</u>
<u>Labour</u>		
1	Renew Aircon Compressor Unit, Air Suction Pipe & Belting	225.00
		<u>1,686.46</u>
7% GST		<u>118.05</u>
Total		<u>1,804.51</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SNW 2051PWIP: 61000

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Hose, A/C compressor suction	? / <u>SUPP</u>		/ <u>TL</u>	7815 A 888 } Steve 28/12/20
2	Belt, Alternator & others	? / <u>SUPP</u>	<u>Steve 28/12/20</u>	/ <u>TL</u>	1340 A 249. } Steve 28/12/20
3	Air GULK RH - (628178)	? / SUPP	- /	- / <u>RR</u>	Steve 28/12/20
4	Arm Assy, FR. susp, LWR. RHT	? / SUPP		/ <u>RT</u>	4013 A 310
5	Crossmember, FR. Axle No. 1	? / SUPP		- / <u>RT</u>	4000 A 1449. } Steve
6	Compressor Assy A/C	? / <u>SUPP</u>		/ <u>RT</u>	7813 A 980 } 7/1/20
7	LABOUR R/T A/C compressor unit,	? / SUPP	8225	-	
8	air-con suction pipe & belting	? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	28/12/20	Steve 9:45 AM
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: averageSURVEYOR: Steve

Work Order: R001301
 License: SMW 2051 P
 Technician: 106 WENG SOON
 Mileage: 2639
 Date: 7.1.21 8:50

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°31'	-0°32'	-0°40' 0°50'
3°55'	3°55'	3°15' 4°45'
-0°01'	0°09'*	-0°07' 0°07'
12°11'	12°11'	10°05' 13°05'
11°40'	11°40'	9°25' 13°55'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°25'	-0°36'	-0°40' 0°50'
4°36'	4°36'	3°15' 4°45'
0°00'	-0°10'*	-0°07' 0°07'
10°18'	10°29'	10°05' 13°05'
9°53'	9°53'	9°25' 13°55'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°06'	0°04'	-0°30' 0°30'
-0°41'*	-0°41'*	-0°30' 0°30'
1°53'	1°42'	
-0°01'	-0°01'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°53'	-0°53'	-1°45' -0°15'
0°11'	0°11'	-0°01' 0°13'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°18'	-1°18'	-1°45' -0°15'
0°05'	0°05'	-0°01' 0°13'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°25'	0°24'	-0°30' 0°30'
0°16'	0°16'	-0°02' 0°26'
0°03'	0°03'	

Work Order: R001301
 License: SMW 2051 P
 Technician: 106 WENG SOON
 Mileage: 2639
 Date: 7.1.21 8:50

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Front : Left

Actual	Before	Specified Range
-0°31'	-0°32'	-0°40' 0°50'
3°55'	3°55'	3°15' 4°45'
-0°01'	0°09'	-0°07' 0°07'
12°11'	12°11'	10°05' 13°05'
11°40'	11°40'	9°25' 13°55'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°25'	-0°36'	-0°40' 0°50'
4°36'	4°36'	3°15' 4°45'
0°00'	-0°10'	-0°07' 0°07'
10°18'	10°29'	10°05' 13°05'
9°53'	9°53'	9°25' 13°55'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°06'	0°04'	-0°30' 0°30'
-0°41'	-0°41'	-0°30' 0°30'
1°53'	1°42'	
-0°01'	-0°01'	-0°14' 0°14'

Rear : Left

Actual	Before	Specified Range
-0°53'	-0°53'	-1°45' -0°15'
0°11'	0°11'	-0°01' 0°13'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°18'	-1°18'	-1°45' -0°15'
0°05'	0°05'	-0°01' 0°13'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°25'	0°24'	-0°30' 0°30'
0°16'	0°16'	-0°02' 0°26'
0°03'	0°03'	

All DTCs

2021.01.06

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2021MY

SMW 2051 P.

→ M.U.T. III Diag. - ok.

→ Read DTC only - Before -

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs		
AT/CVT/A-MT/TC-SST	KOSOSS_99880010		No DTCs		
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs		
ABS/ASC/ASC/STC/WSS	KOSOSS_99880010		No DTCs		
SRS-AIR BAG	KOSOSS_99880010		No DTCs		
Air Conditioner	KOSOSS_99880010		No DTCs		
ETACS	KOSOSS_99880010	B1707	Flasher open	Active	
Meter	KOSOSS_99880010		No DTCs		
Steering Angle Sensor	KOSOSS_99880010		Non-target System		
KOS/OSS/IMMO/keyless (with KOS)	KOSOSS_99880010		No DTCs		

All DTCs

2021.01.06

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	A13A 2021MY

SMW 2051 P.

⇒ H.U.T. III Diag. chk.

Is Read & clear DTC.

After

All DTCs

2021.01.06

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition		
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCs			
AT/CVT/A-MT/TC-SST	KOSOSS_99880010		No DTCs			
4WS/Electric Power Steering	KOSOSS_99880010		No DTCs			
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCs			
SRS-AIR BAG	KOSOSS_99880010		No DTCs			
Air Conditioner	KOSOSS_99880010		No DTCs			
ETACS	KOSOSS_99880010		No DTCs			
Meter	KOSOSS_99880010		No DTCs			
Steering Angle Sensor	KOSOSS_99880010		Non-target System			
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCs			