

ASS. REC. BY:

Stein

REF:

A16

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKO 6220

Yr Regn:

23/1/19

Type: M.Crr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c

1591

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

27761

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNA F3416 MK S927328

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

20/12/21

D.O.I.

21/12/21

Survey held at

Cycle & Caravan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MK-73K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Rep. Forms:

Comp Sum / L.E. / P.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08235/CHEW CHIN SENG Reg No/Reg Date SKD622D / 23/01/201 Date In/Mileage / 27761 Chassis No KNAF3416MK5027328 Engine No G4FGJH716014 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	21/12/2020/ 12:07	QUD	247 / DonBong	26096		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							800 1600.00
RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR, RH MIRROR				400x1			
RH REAR DOOR: REPAIR RH REAR FENDER							120.00
E PNT88000							
TRANSFER RH FRONT DOOR GLASS, DOOR TRIM, MECHANISM							120.00
AND OTHERS ATTACHMENT TO NEW DOOR PANEL							
E PNT88000							
TRANSFER RH REAR DOOR GLASS, DOOR TRIM, MECHANISM							2880.00
AND OTHERS ATTACHMENT TO NEW DOOR PANEL							
E PNT98000							1920
PAINT WORK SPRAY RH MIRROR, RH FRONT DOOR, RH REAR DOOR,				480 X 4 (CR5 color)			
RH REAR FENDER, RH SIDE SILL AND AFFECTED PORTION							80 120.00
(CLEAR COAT)							
M SUNDRY							30.00
APPLY BODY SEALANT							
A 54900099							80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							120.00
PERFORM RUST PREVENTION							
A 10028901							120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
A WHEELALIGNMENTBP							400.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							30.00
SUPPLY RH REAR SPORT RIM							
M SUNDRY							50.00
LABOUR TO RENEW RH REAR SPORT RIM INCLUDING BALANCING							
M SUNDRY							
SUNDRIES				1.00	1277.00	20.00	1021.60
M PANEL ASSY-FRONT DOOR,RH				1.00	37.00	20.00	29.60
M MOULDING ASSY-FRT DR FRAME,RH				1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR BELT O/S RH							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08235/CHEW CHIN SENG Reg No/Reg Date SKD622D / 23/01/201 Date In/Mileage / 27761 Chassis No KNAF3416MK5027328 Engine No G4FGJH716014 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	21/12/2020/ 12:07	QUD	247 / DonBong	26096		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	GLASS ASSY-FRONT DOOR,RH			1.00	207.00	20.00	165.60
M	PANEL ASSY-FRONT DR MODULE,LH			1.00	241.00	20.00	192.80
M	MOTOR ASSY-FRONT POWER WDW,RH			1.00	362.00	20.00	289.60
M	BLACK TAPE-FR DR RR,RH			1.00	13.00	20.00	10.40
M	BLACK TAPE-FR DR RR,RH			1.00	13.00	20.00	10.40
M	BLACK TAPE-RR DR FRAME RR OTR,			1.00	8.00	20.00	6.40
M	PANEL ASSY-REAR DOOR,RH			1.00	1377.00	20.00	1101.60
M	W/STRIP ASSY-RR DR BELT O/S RH			1.00	60.00	20.00	48.00
M	MOULDING ASSY-RR DR FRAME,RH			1.00	44.00	20.00	35.20
M	FILM-ANTI CHIPPG RH			1.00	27.00	20.00	21.60
M	MIRROR ASSY-OUTSIDE RR VIEW,RH			1.00	559.00	20.00	447.20

Estimate

SURVEYOR NAME: Stere CLKK)
SURVEYOR SIGNATURE: DD - NA Anti
DATE: Excess - ?
REMARKS: P/P
By Bel
S dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Confirm & accepted by Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Authorized signatory and company stamp

	Nett	9,101.20
7% GST on	9101.20	637.08
Total Payable		9,738.28

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CL0006 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
DATE & TIME: 21/12/2020 13:56 (SGT)
SUBMITTED BY: TAN SHIEH YUEN
VERSION: 1 (21/12/2020 13:56 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident
Exact Location of Accident
Additional Location Information
Country/State of Loss

21/12/2020 13:56 (SGT)
20/12/2020 10:14 (SGT)
Bedok South Ave 1, Singapore
BEDOK SOUTH AVENUE 1 TOWARDS NEW UPPER CHANGI
ROAD
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKD622D

INSURED/POLICYHOLDER

Is company?
Name Of Registered Owner
NRIC No
Email Address
Mobile Phone No
Alternative Phone No

No
CHEW CHIN SENG
SXXXX634F
maxcty@gmail.com
(Phone) +65-90293688
+65-90293688

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category

Kia
Cerato
-
Private use
Yes
Private car

INSURANCE COMPANY

Name of Insurance Company
Type of Coverage
Fleet Policy
Policy Number
Cover Note Number

AIG
Comprehensive
No
1900007951
-

DRIVER

Name of Driver
NRIC No
Date Of Birth

CHEW TIAN YEOW
SXXXX629E
18/01/1983

Indoor
17/01/2004
16 YEARS AND 11 MONTHS
Male
(Phone) +65-98411983

maxcty@gmail.com
BLK. 187A BEDOK NORTH STREET 4
#12-32 SINGAPORE
461187

No
Child
No

-
-

Collision - Change/cross lane
Clear
Dry

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 4
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name
Gender

MERRI
Female

PASSENGER 2

Name
Gender

CASPER CHEW
Male

PASSENGER 3

Name
Gender

CAMILLE CHEW
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Registration Number
Manufacturer
Model
Variant
Colour
Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SHC994X
Hyundai
I40
-
Yellow
Taxi
TEO SA WAH
(Phone) +65-96724517

-
-
-
First Capital
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 21/12/2020

1040H

Driver's Signature

(If driver is not the policyholder)


Date & Time: 21/12/2020

1040H

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHMENT.

Brief Details

On the 20/12/2020 at about 1014 hrs, I was driving my vehicle (SKD622D, vehicle A) along Bedok South Ave 1 towards New Upper Changi Rd on the left lane. As I was approaching the traffic light, another vehicle (SHC994X vehicle B), which was on the right lane, suddenly swerved into my lane and collided onto the right portion of my vehicle. We then stopped at the roadside and vehicle B's driver and I come down. We then exchanged particulars and we left the scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/12/2020
1040H

Driver's Signature

(If driver is not the policyholder)
Date & Time: 21/12/2020
1040H

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHEW CHIN SENG
Period of Insurance : 23 Jan 2019 To 22 Jan 2021
Engine No. : G4FGJH716014
Chassis No. : KNAF3416MK5027328

Vehicle No. : SKD622D
Policy No. : 1900007951
Endorsement No. :
Issued Date : 30 Jan 2019

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHEW CHIN SENG - \$600 (Own Damage), CHEW TIAN YEOW - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69326000
2. Cycle & Carriage Body & Paint Centre Add: 203 Pandan Gardens Singapore 609339 65634501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622215

C&CKICP2 - MIMILE
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Mile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE