From: Date: Eglinated Cost. OD/TP/WS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: at Workshop m/s of Insured. Policy No Claims No. Claims No. Sum insured: Excess: (Cliont's Record) Make of Veh: Policy Condition] Remark: The veh had commenced its repair at the time of inspection. Ral. or Market Value: IDAC Accident Rport: Consistent?: Yes or No IVeh No. SLA 3918		STEVE Alg	ASSIGNMENT
Estimated Cost (Da/ TP / WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: of Insured: Insu	₩ 21/33		ASSIGNMENT
Truck I Freilar or Market Value: Concord Market Value:		Dale:	1 4 1 4 1 0 11 11 1000
To improve Vehicle No. of Workshop m/s of insured Policy No Cleams No. Sum insured: (Chort's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Policy No. Cleams No. (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Policy No. Cleams No. (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Policy No. Consistent?: Yes or No. DIA / PR Seen: DIA / PR Seen: Consistent?: Yes or No. DIA / PR Seen: Consistent?: Yes or No. DIA / PR Seen: DIA / PR Seen: Consistent?: Yes or No. DIA / PR Seen: Consistent?: Yes or No. DIA / PR Seen: Consistent Instruction The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body Structure affected due to collision The UiC / Chassis frame / Body		ES / OD PEC / EVA / WWW.	
A REV / REP. / 24 HRS Person Contacted: Vehicle: In / Out A REV / REP. / 24 HRS Person Contacted: Vehicle: In / Out A REV / REP. / 24 HRS A Contacted: Vehicle: In / Out A Contacted: True, File Pasts 107 Add Fee: Sheading April: Insured:			Truck / Trailer or
Colour AC: Insured 13rd INI Insured In		0	Make: (1/1 Optima cc 199
Insured Policy No Claims No Sum issured: Excess: (Cliom's Record) Make of Veh: Make of Veh: Repair at the time of inspection. Sal. or Market value: DAC Acadent Rport: Consistant?: Yes or No JIA / PR Seen: Gays Res.: Yes or No JIA / PR Seen:			
Coling No Claims No. Claims No. Claims No. Cloid (Client's Record) Make of Veh: (Policy Condition) Nemaric: The veh had commenced its repair at the time of inspection. Page or Market Value: DAC Accident Roort: Consistent? Yes or No DIA / PR Seen: Consistent? Yes or No DIA / REP. / 24 HRS Wehicle: IN / OUT The "Urc / Chassis frame / Body Structure effected due to collisit frame / Body Structure effected due to collisit frame, File Resium 167 Add Fee: Site insp (\$			
Gen. Conditional Gen. Conditional Steering: Integrate / Jammed / Leaked / Burnt or Mode: Nil / Signific / Jammed / Leaked / Burnt or Mod: Nil / Signific / Jammed / Leaked / Burnt or Mo	Policy No	211 No. 3 to Section 10 . 5 to Section 2 to 100 to	
Stearing: Maske of Veh: Stearing: Morder / Jammed / Leaked / Burnt or Mode: NII / BRm STO ARTIm or Tyre Size: F: // SSE/7	Claims No.		C/NO: KN/AGU411N/45934644
Brake Indider Jammed Leaked Burnt or Modi Nill Street Str	Sum insured:	Excess:	
Modil: Nil 1 679 im 1 STD A/Rim or Tyre Size: F: 1/5/55/7 Remark: The veh had commenced its repair at the time of inspection. Sal. or Market Value: DAC Accident Root: Consistent7: Yes or No SIA / PR Seen: Ven or No SIA / PR Seen: Ven or No SIA / REV / REP. / 24 HRS Person Contacted: Vehicle: IN / OUT Des. of Damages: Frt / Rear / O/S / IN/S / U/C / Rooftop or Real / Interview (\$	(Client's Record)		
Tyre Size: F: Sign File Pass File File Report File Refurn File Refuser File Refu	Make of Veh:	•	
R: The veh had commenced its repair at the time of inspection. Rad. or Market Value: DAC Accident Rport: Consistent? : Yes or No St. Repairs: days Res.: Yes or No St. Repairs: A I REV / REP. / 24 HRS Vehicle: IN / OUT The 'UiC / Chassis frame / Body Structure affected due to collisic alse / Time Accident / Instruction Instruction A Collision A Collision A Collision Instruction A Collision A Collision Instruction A Collision A Collision Add Fee: Site Insp (\$	****		
Remark: The veh had commenced its repair at the time of Inspection. Set. or Market Value:	(Policy Condition)		Tyre Size: F: /////
repair at the time of inspection. Sal. or Market Value: DAC Accident Root: Consistent?: Yes or No BABI RVBal. Mm RVBal. Mm RVBal. Mm RVBal. Mm RVBal. Mm RVBal. D.O.A. D.O.I.	7.4 - C.	mmoncod ite	
Rail or Market Value: DAC Acddent Rport: Consistent?: Yes or No SIA / PR Seen: Consistent?: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No SIA / PR Seen: Gays Res.: Yes or No Survey held at Cycle Call was Des. of Damages: Frt / Rear / O/S / N/S / U/C / Reoftop or Sia / Time Action / Instruction MV - CSA The U/C / Chassis frame / Body Structure affected due to collising frame / Bod		,	DO TOUR PEANOVAT GY FFS / LIZA / MIC / OHTSU / PIR / SUMI /
DAC Accident Roort: Consistent? : Yes or No IIIA / PR Seen: Consistent? : Yes or No IIIA / PR Seen: Consistent? : Yes or No IIIA / PR Seen: May Res.: Yes or No IIII / PR Seen: May Res.: May Lead of No. O.		× 1	TOYOTYOKO or \$ Kun ho
IN / PR Seen: Consistent? : Yes or No st. Repairs:days Res.: Yes or No JOA	Ral. or Market Value:		Fron! Rear
SIRE PERSONS Consistent?: Yes or No SIRE Repairs: days Res.: Yes or No D.O.A. JILLY Survey held at Consistent?: Yes or No Survey held at Consistent?: Yes or No Survey held at Consistent?: Yes or No Survey held at Consistent In Jour Chaissis frame I Body Structure affected due to collisis The Uic I Chaissis frame I Body Structure affected due to collisis The Uic I Chaissis frame I Body Structure affected due to collisis The Pass Lo? Prell. Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$) Sees.	DAC Accident Roort:	Consistent? : Yes or No	R/Bal, mm R/Bal.
St. Repairs: days Res.: Yea or No	SIA / PR Seen:	Consistent?: Yes or No	1/80
Survey held at	st. Repairs;	days Res.: Yes or No	- atiata
Des. of Damages: Frt Rear O/S N/S U/C Rooftop or Rear Time Action / Instruction MV - 68 Report Prell. Report Resurvey No. of Trip: Survey Fee: Transportation: See Resurvey No. of Trip: See Resurvey No. of	ım Sum;	% 3 Val.: Yes or No	- John Cock College
Vehicle: IN / OUT The 'U/C / Chassis frame / Body Structure affected due to collisis Action / Instruction MV - ES K Time, File Pass to? Prell. Report Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Stile Insp (\$) Fhotos Fhotos Trach, Invertige Trach, Invertige Trach, Invertige Protos Stile Insp Protos Protos Protos Protos Stile Insp Protos	A / REV / REP /	24 HRS	- \
Date / Time Action / Instruction MV - 68 K Tame, File Pass 107 Prell Report Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee: Transportation: Transportation: Survey Fee: Transportation: Survey Fee: Survey Fee: Transportation: Survey Fee: Survey		Vehicle: IN / O	00. [1]
Action / Instruction MV - 68 K Fine, File, Pass 107 : Prell. Report Days Of Repair: Survey Fee: Transportation: Transportation: Add Fee: : Site Insp (\$) .s. +Rssi Interview (\$) Fhotos Transportation: The fine Return to?	ile:Perso	on Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Time, File Pass to? Prell. Report Days Of Repair: Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site insp (\$		struction	
Tane, File Pass 107 : Prell. Report Days Of Repair: : Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: : Site Insp (\$)	<u> MV-</u>	68 K	
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Enterview (\$) Enterview (\$)			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Interview (\$) Photos Cities C			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Interview (\$) Photos Cities C			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Enterview (\$) Enterview (\$)			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Enterview (\$) Enterview (\$)			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Interview (\$) Photos Cities C			
Final Report Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)s+Rs_si Interview (\$) Photos Cities C			
Time, File Return to? Survey Fee: Transportation: Survey Fee: Transportation: State Insp. (\$)s + Rsst			
Add Fee: Site Insp (\$) s+RS_Si Interview (\$) Photos Transportation: S+RS_Si Photos Transportation: S+RS_Si Photos			
Add Fee: Site Insp (\$)_s+Rs_si : Interview (\$) Photos : Tech. Inve (8) Others	Time, File Pass to?	: Prell. Report	Days Of Repair:
Add Fee: Site Insp (\$) s+Rs_si : Interview (\$) Photos : Tech. Invs (8) Offices	Time, File Pass to?		
: Interview (\$) Photos : Tech. Invs (\$) Offices	<u> </u>		Resurvey No. of Trip: Survey Fee:
Tech. Invs (3) Others	<u> </u>	: Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
	<u> </u>	: Final Report	Resurvey No. of Trip: Survey Fee: Transportation: s + RS_Si
	Tune, File Return to?	: Final Report	Resurvey No. of Trip: Survey Fee: Transportation: Site Insp (\$) _ s + Rs _ Si Interview (\$) Photos



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

No : 199405410K Involce Name & Address	Owner Name & Vehicle Info			
	Cust No/Name	/Dufu Industries Services Pte.		
AIG Asia Pacific Insurance Pte.	Reg No/Reg Date	SLA3918K / 29/02/201		
Ltd. MOTOR CLAIM DEPARTMENT	Date In/Mileage Chassis No			
78 SHENTON WAY #08-16				
AIG BUILDING		G4NDFH092301		
SINGAPORE 079120	Make/Model	KIA/OPTIMA 2.0 A 707		
Contact No 64191000	Colour/Trim	ABP / WK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
LAX00000	Credit	21/12/2020/ 12:54	BLE	261 / Edwin Caina		26097			
LARCCCC	Credite	Description of Good	s / Services		Qty	Unit Price			600.00
E PNT88000 REMOVE & A 54900099 CHECK WII A 10028901 TO CARRY USING HI- M SUNDRY APPLY AN' M SUNDRY SUNDRY SUNDRY SUNDRY FAPLY AN' M PAD-DOOR M PAD-DOOR M PAD-DOOR M PANEL AS M MOULDING M GARNISH M MOULDING	HR FENDER I LHR DOOR REFIT LH RING ELEC OUT DIAC -SCAN PRO TI CORROS TI CORROS OUTSIDE DR O/S HANI SY-REAR I ASSY-RR ASSY-RR ASSY-RR -RR DR O	& LHR FENDER HR DOOR COMPONENT CTRICAL SYSTEM GNOSTIC CHECK USING TEST OUTSIDE, LH HANDLE, LH HOLLH DIE REAR, LH OOR, LH OOR, LH OR FRAME, LH	HI-SCANTPRI		1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	55.00 3.00 25.00 3.00 1307.00 132.0 104.0 126.0 22.0	0 20.00 0 20.00 0 20.00 0 20.00 0 20.00 0 20.00 0 20.00 0 20.00	40 20	700.00 120.00 30.00 120.00 30.00 44.00 2.40 20.00 2.40 1045.60 105.60 83.20 10.80 17.60 62.40
the Re • To resi • To disp	pairer of the urvey before/a play damaged prices are sub	SURVEYO SURVEYO DATE: by ants hence notify MARKS e following: after spray painting part(s) during resurvey ject to confirmation on a "Without Prejudice" basis	R SIGNATURE	Steve CLKK) EXCITION PIP By By C. Sy 4 Js	7 A.L.		Nett 4.00		4,164.0 291.4 4,455.4

Validity of this estimate is 124 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding 651. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewithe rubber seal or other repair requiring the removal of the windscreen.

A20CL0009-01 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD fRY DATE & TIME: 21/12/2020 15:10 (SGT) // OBMITTED BY: TAN SHIEH YUEN VERSION: 2 (21/12/2020 16:41 (SGT))



SINGAPORE ACCIDENT STATEMENT

MPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Ine issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any felse reporting may be referred to the Police for Investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

21/12/2020 15:10 (SGT) Date of Submission 20/12/2020 08:00 (SGT) Date of Accident 373 Upper Aljunied Rd, Singapore 367859 Exact Location of Accident UPPER ALJUNIED ROAD Additional Location Information Singapore Country/State of Loss

IDETAILS OF OWN VEHICLE

01 420101

Kia

2100452547

Vehicle Registration Number	SLASSISK
INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No Companil Address Mobile Phone No Alternative Phone No	Yes DUFU INDUSTRIES SERVICES PTE LTD 2XXXXX589D ANGIE@DUFU.COM.SG (Phone) +65-98339711 +65-98339711

VEHICLE PARTICULARS

Manufacturer

Mandiacturer	7 <u>2</u> 12
Model	Optima
Variant	•
Exact purpose for which vehicle was being used at time of accident	•
Are you claiming under your own insurance policy for repair to	Yes
your vehicle?	Private car
Pehicle Category	Private car
En	
A second	
INSURANCE COMPANY	
Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No

DRIVER

Policy Number Cover Note Number

Name of Driver	NG HWEE NGEE
PRIC No	SXXXX139F
Date Of Birth	02/12/1967
Occupation	Indoor

Of Driving Pass 20/10/1997 ving experience 23 YEARS AND 2 MONTHS Female ender Mobile Number (Phone) +65-98339711 Alt. Phone Number ANGIE@DUFU.COM.SG Email Address 16 LEITH ROAD Address Address complement 547921 Postcode is the driver the policyholder? No If No. Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Pedestrian Weather Conditions Clear Dry Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other material or property damaged? No Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? PASSENGER 1 WONG SER YIAN : ame Male Pender PASSENGER 2 WONG CHUN KEET Name Gender DETAILS OF POLICE ACTION Was the accident reported to the police? Traffic Police Police Station Name (Phone) +65-65470000 Police Station Phone No (Fax) +65-65474900 Alt. Police Station Phone No. 10 Ubi Avenue 3 Singapore 408865 **Solice Station Address** Mas notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHMENT ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? IIINJURED PERSONS DETAILS

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:



CRIBE CIRCUMSTANCES OF THE ACCIDENT
My relicle was moving along Mejer Aljunial Road on
a D and towards NIGONESON WALL
laster will 2000 before the traffic light there was a land pour
1. Lt my lar Cleft year fortiles
was a man on the ground. I stopped my vehicle at the needest
but Itop and check upon the man, it seem ville he darked
but they are the same into my vehicle.
ecross the road and bump into my vehicle.
Within 5 minutes SLOF officer who happened to pass by
altibled and rendered efficient to the men the
took him
to for everyor Touther with
Moon rushing my rehicke Cocked of the mustoply I reclised the
Moon ruching my vehicle Content of the
1 is the sale sale sale was the sale of th
After the chulcyp at the clinic, doctor advised us to send him to AAF and make a police vigod therefter.
him to AAF and make a police vigod therefta.
mm 43

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:





1 of 3

police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20201219/2066

No

	- Poport N	C ACCIDENT	Vide Report	No.:			Station Diary No.:	
Date/1 im/ 19/12/202	e Report N 20 15:12	made.	E/20201219		140	Marchael	and the second second second second second	
	it's Partic	ulars	An in the second second	115		The state of the state of	- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Name of NG HWE	Informant:	Police IIII E A SECURE	Address: 16 LEITH R	OAD GI	_ASGOW G	REEN SING	SAPORE 547921	
ID Type /	ID Type / ID No.: NRIC NO / State 139F			: e:		Mobile: 98	339711	
Nationalit			Email:					
Sex: Female	Age:	Date of Birth: 02/12/1967	Type of Info Driver	ormant:		Ti vitalion	/ School Name:	
Race: Chinese	_1	X X	Language: Chinese			Institution	7 3011001 1141110.	
Occupation CLERK	on:		Driving Lice Class: 3	ence Inf	ormation:	Date of E	Expiry:	
			The second second	vana sistematik	The second of th	name of the second second	AND	
eneral In	formation	n of the Accident	Duit	-10	Date/Ti	me or	Type of Location:	
Type of	i ii	n of the Accident njury Attended by Police	Dri	ve:	Date/Ti Accider 19/12/2		Type of Location:	
Type of Accident:	i ii	njury	011	ve:	Accider	nt:	Type of Location:	
Type of Accident: Location:	i ii	njury Attended by Police	Dri	ve:	Accider	nt:	Type of Location	
Type of Accident: _ocation: JPPER A	ļi,	njury Attended by Police	Dri	ve:	Accider	nt:	Road Speed Limit:	
Type of Accident: Location: JPPER A Weather:	LJUNIED	njury Attended by Police	Pri No	ve:	Accider	nt:		
Type of Accident: Location: JPPER A	LJUNIED	njury Attended by Police	Dri No	ve:	Accider	nt:	Road Speed Limit:	

Details of V	ehicle Involved	The second secon		The state of the s	14 4 1	M (December
Vehicle No.	the state of the	Make	Modei :	Color	Condition	No of Passenger
SLA3918K	Car		go ld ,			2

	The state of the control of the state of the
Details of Person Involved	electropation of the control of the
Any Pedestrian Involved: Yes	
No. of Pedestrians Injured: 1	Use of Pedestrian Crossing: Not Available





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20201219/2066

CONTINUATION OF REPORT

river ame	NG HWEE NGEE	the second second		ID No.		S1 139F
elated Vehicle	SLA3918K (Car)		-	Conta	ct No.	98339711
Hospital/Clinic	NIL	e.		Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL
ate Treatment	NIL ted Medical Leave	NIL	Date Disc Degree of	harge Injury	NIL NIL	

Brief Details.

ON ABOVE MENTIONED TIME, DATE AND LOCATION,

I WAS TRAVELLING ALONG UPP ALJUNIED RD, A PEDESTRAIN SUDDENLY DASH OUT FROM THE ROAD SIDE WITHOUT USING THE TRAFFIC LIGHT CROSSING AHEAD AND HIT MY REAR LEFT DOOR. I WAS VERY SURE THAT THE TRAFFIC LIGHT AHEAD WAS ON MY FAVOUR.





3 of 3

Report No. T/20201219/2066

police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: TP / NSPI TEY KE XIAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 19/12/2020 15:12
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMED HUSNUL TAUFIQ BIN MD YUSOF Contact No.: 65476358 Authentication Stamp	Classification Of Case: SINGAPORE POLICE FORCE
IP168	Signature:

. . . Getalegyalegyalge

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder period of Insurance

: Dufu Industries Services Pte Ltd : 01 Mar 2020 To 28 Feb 2021

Sales of the Contract of the

CALL The Control of the

Engine No. Chassis No. : G4NDFH092301

: KNAGU411MG5034644

Vehicle No.

: SLA3918K

Policy No.

: 2100452547-04

Endorsement No.

Issued Date

: 17 Jan 2020

ABOUT THE COVER ASSESSMENT WITH NEW YORKS WESTERNISMENT ASSESSMENT OF THE PROPERTY OF THE PROP Make/Model

Engine Capacity/Tonnage: 1,999.00 CC

: KIA OPTIMA K5 2.0

Driver Restriction

: NA

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2016 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

Any person who is driving on the Policyholder's order or with their permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS TO THE REPORT OF THE PROPERTY OF THE PR Section 1 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2 Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 30 Ubl Rd 3 Singapore 408850 67461000
3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 800 Sin Ming Ave Singapore 575733 69326000

For other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES WHY SHOW THE STATE OF THE ST

Hire Purchase Company/Employer's Loan: MayBank I//Ve hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500710050 C&C FULCO-CORP SALES AIG Asia Pacific Insurance Pte. Ltd. This computer generated document does not require a signature.

22 UBI ROAD 4 FULCO BUILDING SINGAPORE 408817 ANSP - MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd. The two the More than the second territories and territor

SSCNFY