

12/12/2020

REF: CS/CTI20014222/Uvd3

Special Instruction:

ASS. REC. BY:

SURVBY

ASSIGNMENT (Office)

Merimen

From (Person): TAN KAH LEONG of CTI

Date/Time: 21/12/2020@4.58PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKX 6308S

Insured: YN 8841S

at Workshop m/s EURO SUCCESS

Tel: 9828 9277

of 1 KAKI BUKIT AVE 6# 02-03

Policy No: DMCVSNA00057962004

Claim No: SNM20D204948/C02/TANKI

Sum Insured:

Excess:

D.O.A. 17/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 5PM@21/12/2020

Person Contacted: AH HUAT

Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 22/12/2020
	SKX 6308S-X	
	YN 8841S-CS/CTI20003552/Ksf3n2	DOA: 07/01/2020
29/12/20	Send IA via merimen	