

12/12/2020

REF: CS/AGI20014225/d3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): IVY RATILLA

of AGI

Date/Time: 21/12/2020@4.33PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMF 9813B

Insured: SJK 8785P

at Workshop m/s

TAN LIM MOTOR

Tel: 6858 5151

of

NO. 1 DEFU LANE 6

Policy No:

Claim No: C10008427/LA

Sum Insured:

Excess:

D.O.A. 20/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

'WP'

H.O.D. Endorsement:

Date/Time 4.47PM@ 21/12/2020

Person Contacted: WILLIAM

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (☒) Estimate	Repairer agreed to survey on 22/12/2020
	SMF 9813B-X	
	SJK 8785P-X	