

6ul.
PRS
Date:
Estimated Cost:
TP/WS/TP RES/OD RES/EVA/INV/MV
Inspect Vehicle No:
Workshop m/s: Apex

Insured:
Policy No:
Claims No:
Insured:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

al. or Market Value: \$73K
JAC Accident Report: Consistent? : Yes or No
JIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 15 days Res.: Yes or No
um Sum: % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Date / Time	Action / Instruction
	CoB: 33.002
	\$14K - \$15K.

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
Date/Time, File Return to?
24/12/20-Typist

CTI
ASSIGNMENT

26 Dec 2019
Veh No: SMR2500L
Type: M/Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Suzuki swift
Colour: Silver
Sp Reading: T
Eng/No: ZC 533 117547
C/No:
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/55 R16
R: 11
BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or
Front
R/Bal: 6 mm
L/Bal: 6 mm
D.O.A.
Survey held at: w/s 112/10
Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: 15
Resurvey No. of Trip:

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Test \$
☐ Transport \$

Survey Fee:
Transportation:
3-PS: \$1
Photo:
Other: