

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	NCE BHD	Ref:	CS/LPC20014269/Ktf3e2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555	Date:	22/01/2021	
			Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJN 4889J	Veh. Inspected	SJM 2772E	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	20/20/21/VP05/024027	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	22/12/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS (A)	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	MR053ZEE106125839	Colour	METALLIC GREEN	
	Odometer	175330 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	DUNLOP	8 mm	
	L/H Front Tyre	205/55 R16	DUNLOP	8 mm	
	R/H Rear Tyre	205/55 R16	DUNLOP	8 mm	
	L/H Rear Tyre	205/55 R16	DUNLOP	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/12/2020	Inspection Date	22/12/2020	
	Survey held at	YEE AUTO PTE LTD			
	160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				