



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 10/02/2021

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG5870K
Case Reference Number	BUS/12/20/5015
Registration Date	16/11/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	A95 MAN E6
Name of Driver	Wang Tao
Type of Accident	Side Swipe
Accident Date and Time	10/12/2020 7:04 PM
Accident Reported Date and Time	14/12/2020 10:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109197
Special Instruction to ARC, if any	SG5870K-RIGHT REAR PORTION SLC7709K (TP) INSURED WITH AIG
Prepared Date and Time	18/12/2020 11:49 AM
Chassis Number	WMAA95ZZ8G7003550
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$345.60	\$345.60
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,572.60	\$1,137.60
Lump Sum Total	\$0.00	\$1,150.00
Number of Repair Days	2.0	1.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	18/12/2020 11:51 AM	18/12/2020 2:09 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 10/02/2021

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00 ✓
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$432.00	\$262.00 ✓
Total Spray Painting & Panel Beating	\$432.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense


Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012636	VE		REVERSE LAMP BULB (A95 MAN)	1.00	\$235.00	10.00	\$211.50	Replace	Replace / CRA
6012635	VE		REAR LAMP BULB (A95 MAN)	1.00	\$245.00	10.00	\$220.50	Replace	Replace / CRA
Total					\$480.00		\$432.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



2/5
\$1,150
1 days

432
-20%
845.6
530
262
1,137.6