

PRQ
PRS

SMO
ASSIGNMENT

20 Jan 2012

Estimated Cost
TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:
Workshop m/s Carsmith

Insured:
Policy No.
Claims No.
Insured:
(Client's Record)
Make of Veh:

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

al. or Market Value: \$28k
JAC Accident Report: Consistent? : Yes or No
iA / PR Seen: Consistent? : Yes or No
st Repairs: 4 days Res.: Yes or No
um Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: Person Contacted Vehicle: IN / OUT

Veh No: SKG67134
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: BMW 116i cc: 1598
Colour: Grey
Sp Reading: 149451
Eng/No: WBA1A2030E948896
C/No:

Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/40ZR18
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. D.O.I. 22/12-20

Survey held at: W/S 4:30pm
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COT: 20509
	\$7000 - \$8000

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

Days Of Repair:
Resurvey No. of Trip:

Adm Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Follow up (\$)

Survey Fee:	
Transportation	
3 + RS	
Food	
Other	