CS3/CT 20014285/Gqd3 | T (-2023)

ASSIGNMENT

Rec. By: fel. PRS

Date:

Veh No: SLE9307M   Regn: 06 May 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make: Honda Fit 1.3cc 1339

Inspect Vehicle No:

Colour: yellow   A/C: Insured / Std / NI / NA

Workshop m/s: Hup Ley Huat

Sp Reading: 177695   T/Radio: Insured / Std / NI / NA

Eng/No:

Insured:

C/No: GE 6603203?

Policy No. DMPCSNW001588 07000

Gen. Cond: Good / Fair / Poor / Burnt

Claims No. SNM20D704935C02

Steering: Inorder / Jammed / Leaked / Burnt or

Sum Insured: Excess:

Brake: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Modi: Nil / S/Rim / STD A/Rim or

Make of Veh:

Tyre Size: F: 195/55R15

R: 〃

(Policy Condition)

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Remark: The veh had commenced its repair at the time of inspection.

Val. or Market Value: $15K

Front: R/Bal. 6 mm; L/Bal 6 mm

Rear: R/Bal. 6 mm; L/Bal 6 mm

OAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

D.O.A.   D.O.I. 28-12-20

Est. Repairs: 5 days   Res.: Yes or No

Survey held at: w/s   12pm

Lum Sum: %   3 Val.: Yes or No

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Frt

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date: Person Contacted:

Date / Time	Action / Instruction
	COE: 8562
	$2000 – $3000
	Submit PRS.

Date/Time, File Pass to?   : Preli. Report

29/12   : Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: Site Insp (S$ Interview (S$

Mer-PRS