

ASSIGNMENT

Ignated Cost

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s

FC Garage

ured:

olicy No.

aims No.

C10008449/KY

im Insured:

Excess:

(Client's Record)

ake of Veh:

(Policy Condition)

emark: The veh had commenced its repair at the time of inspection.

al. or Market Value:

\$80K

JAC Accident Rpt:

Consistent?: Yes or No

IA / PR Seen:

Consistent?: Yes or No

st. Repairs:

4

days

Res: Yes or No

um Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted

Date / Time

Action / Instruction

COB: 34129

Guo Qiang finalised LS \$4900, 4 days (Red \$9591.75, 66%)

Date/Time. File Pass to?

09/06 Typist

Date/Time. File Return to?

☐ : Preli. Report

☐ : Final Report

TP

4900

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ Site Insp (\$

☐ Interview (\$

☐ ... (\$

☐ ... (\$

Survey Fee:

Transportation

...

...

...

Vehicle

Type: M/Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 523i 2.5cc 2497

Colour:

Black

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

Sp Reading

Eng/No:

C/No:

WBAFP320 90C547171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/35ZR19

R:

M

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FIRENZA

Front

Rear

R/Bal.

R/Bal.

mm

mm

L/Bal.

L/Bal.

mm

mm

D.O.A.

D.O.I.

23-12-20

Survey held at

w/s

12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s nt

The U/C / Chassis frame / Body Structure affected due to collision.