

ASS. REC. BY:

*P. Ann*

REF:

CC3/AH20014317/Riba3

088Z

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 3727M

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: AH

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

*2pm over mtg*

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 53K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLG 3727M Yr Regn: 2016 / SGP

Type:  Car /  M.Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: VOLKSWAGEN POLO GP / 2TSI c.c. 1197

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 69502 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: NVWZZZBRZ9U067210

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 19/12/2019 D.O.I. 28/02/2020

Survey held at Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit = 18K</u>

Date/Time, File Pass to?  : Prel. Report  : Final Report

Days Of Repair: \_\_\_\_\_ Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to? 1) \_\_\_\_\_ 2) \_\_\_\_\_

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee:	
Transportation:	
S + RS:	SI
Photos	
Others	
TOTAL	

Repair Format: \_\_\_\_\_ Lump Sum / B.B. (\$) \_\_\_\_\_

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
 Singapore 159934  
 Biz. Reg. No.: 199101494Z  
 GST No.: M200985052



## Quotation

Non binding - Preview

Page 1/2

Company  
 AIG ASIA PACIFIC INSURANCE P/L  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120

Customer Details:  
 Ms.  
 TAN  
 SZE KIAH  
 213 FERVALE CLOSE  
 #12-07  
 Singapore 797461

Document no.  
 Document date  
 Customer no.  
 Customer GST-ID  
 Dealer  
 Job order number  
 Job order date  
 Service Advisor

22-12-2020  
 5211043795  
 201009404M  
 201009404M  
 30001  
 2020035448/ 1  
 22-12-2020  
 TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SLG3727M	6C13EZ	28-09-2016	WWWZZZ6RZGU067210	POLO 1.2 BMT COMFO 66 D7F	66,417

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Wheel Alignment	1	pcs.	360.00	#1	360.00	385.20
	Wheel Balancing	1	pcs.	50.00	#1	50.00	53.50
6R4831056J	Door RHF <i>3 bt</i>	1	pcs.	1,604.45	#1	1,604.45	1,716.76
6R4837697A 5AP	Door Seal Outer Black RHF DOOR SEAL <i>? new</i>	1	pcs.	62.37	#1	62.37	66.74
N 90994201	Pop-Rivet <i>new</i>	4	pcs.	1.14	#1	4.56	4.88
6R4833056J	Door RHR <i>3 bt</i>	1	pcs.	1,604.45	#1	1,604.45	1,716.76
6R6839698A 5AP	Door Seal Outer Black RHR DOOR SEAL <i>? new</i>	1	pcs.	85.67	#1	85.67	91.67
D 378500A2	Sound Absorber Laminated <i>new</i>	2	pcs.	41.40	#1	82.80	88.60
6C0945096L	Taillight With Rear Fog L RHR <i>? repair</i>	1	pcs.	294.62	#1	294.62	315.24
311601361	Rubber Valve <i>new</i>	1	pcs.	3.29	#1	3.29	3.52
6R0601025N AX1	Alloy Wheel Black-Glossy <i>new</i>	1	pcs.	1,360.27	#1	1,360.27	1,455.49
	LABOUR	5	pcs.	840.00	#1 <i>2500</i>	4,200.00	4,494.00
	TRANSFER DOOR MECHANISM	2	pcs.	840.00	#1 <i>840</i>	1,680.00	1,797.60
	Spray Painting	6	pcs.	800.00	#1 <i>2400</i>	4,800.00	5,136.00
	AIG DIRECT SETTLEMENT DOA : 19/12/2020 TP VEH : SJD9992M SURVEY BY :						

Quotation valid till 29-12-2020

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	1,170.00	15,782.48	7%	1,186.67	16,952.48	18,139.15
<b>Total</b>	<b>1,170.00</b>	<b>15,782.48</b>	<b>7%</b>	<b>1,186.67</b>	<b>16,952.48</b>	<b>18,139.15</b>

Customer

Service Advisor

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



SKODA Commercial Vehicles

## Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	22-12-2020
Customer no.	5211043795
Customer GST-ID	201009404M
Dealer	30001
Job order number	2020035448/ 1
Job order date	22-12-2020
Service Advisor	TIOW CHUAN CHEE

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Ms.  
TAN  
SZE KIAH  
213 FERVALE CLOSE  
#12-07  
Singapore 797461

License plate	Model code	First registration	VIN	Model	Mileage
SLG3727M	6C13EZ	28-09-2016	VVVWZZZ6RZGU067210	POLO 1.2 BMT COMFO 66 D7F	66,417

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](https://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](https://volkswagen.com.sg) and [www.skoda.com.sg](https://www.skoda.com.sg) (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Praveen*  
*Hp 90010068*  
*5-6 days*  
*28/12/2020*  
*@ 1400*  
*Resy before paint*

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	21/12/2020 14:48 (SGT)
Date of Accident	19/12/2020 21:00 (SGT)
Exact Location of Accident	Tampines Ave 9, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLG3727M

### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Tan Sze Kiah
NRIC No	SXXXX088Z
Email Address	xonice@gmail.com
Mobile Phone No	(Phone) +65-97233471
Alternative Phone No	(Home) +65-97233471

### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Polo
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	EQ
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPPHQ20-006247
Cover Note Number	-

### DRIVER

Name of Driver	Tan Sze Kiah
NRIC No	SXXXX088Z

Year Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode

12/08/2003  
17 YEARS AND 4 MONTHS  
Female  
(Phone) +65-97233471  
(Home) +65-97233471  
xonice@gmail.com  
23 Fernvale Close #12-07  
-  
797461  
Yes  
-  
No  
-  
-

Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Side Swipe  
Weather Conditions Clear  
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other material or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

PASSENGER 1

Name unknown  
Gender Male

DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

refer attached report.

ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? Yes  
Was there any audio recorded? No

**DETAILS OF OTHER VEHICLE PROPERTY**

Vehicle Registration Number SJD9992M  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category Private car

Contact Number  
Address  
Address complement

Postcode  
Insurance Company Name

Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

(Phone) +65-92250080

-  
-  
-  
-  
-  
-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time: 21/12/20

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

▼

**From:** [chi\\_wai](#)  
**To:** [xonice@gmail.com](mailto:xonice@gmail.com)  
**Subject:** Quotation  
**Date:** Tuesday, December 22, 2020 11:24:34 AM

---

Dear Janice,

We are pleased to quote as following

1. 3x panels 2stage polishing and recoat with CQuartz UK3.0.

Price @ 280sgd  
Downtime @ 5hrs

Quotation valid for 90days.

Regard,  
Chris  
AbsoLust CarCare LLP  
+65 83638893



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC  
Owner ID: 088Z

Vehicle No.: SLG3727M  
Vehicle to be Exported: No  
Intended Deregistration Date: 28 Dec 2020  
Vehicle Make: VOLKSWAGEN  
Vehicle Model: POLO GP 1.2 TSI A/T 6C13EZ SR LED  
Primary Colour: Red  
Manufacturing Year: 2016  
Engine No.: CJA62826  
Chassis No.: WWWZZZ6RZGU067210  
Maximum Power Output: 66.0 kW (88 bhp)  
Open Market Value: \$17,279.00  
Original Registration Date: 28 Sep 2016  
First Registration Date: 28 Sep 2016  
Transfer Count: 0  
Actual ARF Paid: \$7,279.00

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 27 Sep 2026  
PARF Rebate Amount: \$5,459.00

COE Expiry Date: 27 Sep 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$50,000.00  
COE Rebate Amount: \$28,748.00  
Total Rebate Amount: \$34,207.00

The information contained herein is correct as at 28 Dec 2020

OK

Red



Merimen e-Claims



Used 2016 Volkswagen Polo GP



PARF/COE Ret

mart.com/used\_cars/info.php?ID=938744&DL=1149

# Volkswagen Polo GP 1.2A TSI Sunroof

- Overview**
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

<b>Price</b>	\$53,888		
<b>Depreciation</b> ?	\$8,480 /yr View models with similar depre	<b>Reg Date</b>	30-Nov-2016 (5yrs 11mths 1day COE left)
<b>Mileage</b>	59,876 km (14.7k /yr)	<b>Manufactured</b> ?	2015
<b>Road Tax</b> ?	\$508 /yr	<b>Transmission</b>	Auto
<b>Dereg Value</b> ?	\$35,667 as of today (change)	<b>OMV</b> ?	\$17,316
<b>COE</b> ?	\$50,951	<b>ARF</b> ?	\$7,316
<b>Engine Cap</b>	1,197 cc	<b>Power</b>	66.0 kW (88 bhp)
<b>Curb Weight</b> ?	1,139 kg	<b>No. of Owners</b> ?	1
<b>Type of Vehicle</b>	Hatchback		

## Features

Powerful 88 Bhp 160 Nm 1.2 TSI Engine With 7 Speed DSG Gearbox. Nippy, Dynamic Drive With High Specs. Excellent Low Fuel Consumption Of 21km/L View specs of the Volkswagen Polo (2009-2018)

## Accessories

Leather Seats, Alloy Rims, Factory Audio Systems, LED Headlights. Auto Side Folding Mirrors. Knockdown Rear Seats, ISOFIX And Reverse Sensors, Sunroof

