SA01211D0006 / AIG Asia Pacific Insurance Pte. Ltd. ENTRY DATE & TIME: 13/01/2021 11:50 (SGT) SUBMITTED BY: Paramchand, Varsha VERSION: 1 (13/01/2021 11:50 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 13/01/2021 11:50 (SGT) Date of Accident 17/12/2020 20:00 (SGT) Exact Location of Accident Singapore Additional Location Information bali lane Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLC2487H

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner Nicholas Giles Aplin NRIC No. S2638839B Email Address nick.aplin59@gmail.com Mobile Phone No (Phone) +65-67633677

Alternative Phone No +65-67633677

VEHICLE PARTICULARS

Manufacturer Toyota Model Corolla Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? No - Reporting only Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG Type of Coverage Comprehensive Fleet Policy

Policy Number 2100464735-04

Cover Note Number

DRIVER

Name of Driver Nicholas Giles Aplin NRIC No S2638839B Date Of Birth 07/03/1952 Occupation Indoor

Date Of Driving Pass 26/04/2013 Driving experience 7 YEARS AND 8 MONTHS Gender Mobile Number (Phone) +65-67633677 Alt. Phone Number +65-67633677 Email Address nick.aplin59@gmail.com Address 97 Cashew Road Address complement #03-03 SINGAPORE Postcode Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Parked Vehicle Weather Conditions Clear Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Nο PASSENGER 1 Name claudia tan Gender **Female DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Traffic Police Police Station Phone No (Phone) +65-65470000 Alt. Police Station Phone No (Fax) +65-65474900 Police Station Address 10 Ubi Avenue 3 Singapore 408865 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT R2000006970 Circumstances Of Accident There were no parking lots along the lane (Bali Lane/Carpark). Tried to exit the road but it was extremely tight and congested with pedestrians and other vehicles. There were tables of F&B patrons along the side of the road. A member of the public assisted in giving hand signals to manoeuvre out. Vehicle might have touched a parked car. I had no idea at the time because the car was moving very slowly. There was no noise caused by any impact. The member of the public continued to assist until I was able to manoeuvre out. ATTACHMENT(S) Are accident photos available for attachment? No Was there any video captured by Car Camera? No Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

SMT 9201T

Vehicle Registration Number

Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



