

Our Job Ref No : 305440294

Date : 29/12/20

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHD3284L

18/12/2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: AIG SGS2118Z

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

\$480.00

Total for Part-By-Part Repair Cost

\$480.00

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : taufikh

Name : Taufikh

Date : 11/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440294
REGN NO : SHD3284L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 08.07.2016
DATE/TIME IN : 21.12.2020 13:30
ACCIDENT DATE : 18.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING	280.00
0001 SP	SPRAYPAINT CHARGE	200.00

SUB-TOTAL : 480.00

TOTAL : 480.00

MVA NAME & SIGNATURE

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

TE :

DATE :