

NATIONAL Assessment Centre Services.

[Part 1 Jan 2005]

SM0920CM0002

Date In: 23/12/20 09:53	Job description	Date & Time Completed	Done by
Ref No: NA/INC 20014334/h4	SAS e-filing		
Veh No: SGT 1243X	E-mail (within 2hrs, AIC 2hrs)		
IP/A: 22/12/20 11:10	I-Motor Claim Form	MT/1114913 901	24/12/20 13:33
TP: TP: Reporting Only	I-Motor W/O (within: OD 2hrs, TP 4hrs)		
TP Insurer:	I-Photo Uploaded		
	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (Tel: (Fax: (
TP Particulars:	Veh No: SHA 877L	INC () / Non-INC ()
Owner / Driver: (Tel: (
Policy No: (Period: (Cover Type: (
Confirmed by: (Date: (Time: (
Insured/Driver Liability: (%) [Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]	
Year of Registration: (Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:
() Walk-In Customer: Customer's Information strictly Confidential & Strictly NO refer of repolier.
() Total Loss Case: to e-mail Insurer URGENTLY.
Drive-In () / Towed-In (); Invoice: YES () / NO (); Towing Co: (

Remarks:	INC () / Non-INC ()
1) Apply for Transport Allowance () / Courtesy Car ()	
2) QC Check / Post Repair Inspection ()	
3) Upload Resurvey Photo [Repair Cost > \$3000] ()	

Injury: ()

Defecting:	Actions:

NA2100742	Invoice Information Checked	30
Driver/Owner:	1) AR: Accident Reporting (\$30)	
Contact No:	2) DA: Damage Assessment (\$100); INC (\$30)	
Damaged Portion:	3) TP: Towing Fee \$40/\$45	
QC Checked by (Engr-In-Charge):	4) PT: Follow-Through Survey \$120	
	5) PT: Follow-Through Survey (Resurvey) \$30	
	For claiming against INC Only (w/c 10 Jan 2005)	
	6) TR: Re-inspection \$75	
	7) NI: Idao DA + SMRT Survey \$160	
	8) NTUC Additional Services:	
	OD:	
	*NS: Courtesy Car / Tpt Allowance \$3	
	*NG: Repair Co-ordination \$10	
	*N7: Post Repair Inspection \$25	
	*N8: DV / Collect Excess Coordination \$3	
	TP (N11): TP (Non INC) against INC \$20	
	9) N12: Idao Mobile \$0	
	Invoice dated	Fee Charged
		Fee Charged

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/12/2020 09:53 (SGT)
Date of Accident	22/12/2020 11:10 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGT1243X
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	GILSELLE WONG SZE QI
NRIC No	SXXXX581B
Email Address	ALOYSIUS.NGUAN@GMAIL.COM
Mobile Phone No	(Phone) +65-96502872
Alternative Phone No	+65-96502872

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Fit
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5120246965
Cover Note Number	-

DRIVER

Name of Driver	NGUAN KANG WEI ALOYSIUS
NRIC No	SXXXX876B
Date Of Birth	21/07/1986
Occupation	Outdoor

Date Of Driving Pass	27/07/2018
Driving experience	2 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90608524
Alt. Phone Number	-
Email Address	ALOYSIUS.NGUAN@GMAIL.COM
Address	BLK 288C COMPASVALE CRESCENT #12-347
Address complement	-
Postcode	543288
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	WIFE
Gender	Female

PASSENGER 2

Name	SON
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bedok North Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002449999
Alt. Police Station Phone No	(Fax) +65-62447258
Police Station Address	30 Bedok North Road Singapore 469676
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT T/20201222/2089

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA877L
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

The sketch plan is drawn on a grid. It shows a horizontal line with a dashed line below it. Below the dashed line, there are two boxes labeled 'A' and 'B' with arrows pointing towards each other. To the right of the grid, the following text is handwritten:

A = SGT 1243X
B = SHA 877L

Describe Circumstances of the Accident

Refer to Police Report T/20201222 / 2089

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20201222/2089

1 of 4

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20201222/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/12/2020 16:27	Vide Report No.: E/20201222/0078	Station Diary No.: 68
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: NGUAN KANG WEI, ALOYSIUS			Address: APT BLK 97 BEDOK NORTH AVENUE 4 #23-1509 SINGAPORE 460097		
ID Type / ID No.: NRIC NO / S8619876B			Contact No.: Home/Office:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/12/2020 11:10	Type of Location: EXPRESSWAY
Location: PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGT1243X	Car	HONDA	FIT	Black	Seriously Damaged	2
SHA877L	TAXI	HYUNDAI		Yellow	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20201222/2089

2 of 4

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20201222/2089

CONTINUATION OF REPORT

Driver				
Name	NGUAN KANG WEI, ALOYSIUS		ID No.	S8619876B
Related Vehicle	SGT1243X (Car)		Contact No.	90608524
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight	
Driver				
Name	ONG ENG YIM		ID No.	S1623561Z
Related Vehicle	SHA877L (TAXI)		Contact No.	96370115
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 22nd December 2020 at about 1110hrs, I was driving my vehicle bearing registration plate number SGT1243X along Pan Island Expressway towards Tuas. I had two passengers with me (My Wife (31YO) and my Son (4.5YO) sitted at the back seat. The road was dry and traffic was heavy at that point of time. I was travelling at the extreme right lane (1st lane)

At the said expressway , (12.5km mark) , there was a yellow colored taxi bearing registration plate number SHA877L who suddenly come to a stop. I tried to break but could not stop in time. As such, a head to rear collision occurred. The impact was great causing massive damage at the front portion of my vehicle.

Traffic police and ambulance came to scene reference (E/20201222/0078). We managed to exchange particulars before leaving the accident scene. My son and the other party's passenger was being conveyed to hospital.

Due to the accident, I strained my neck. However, I have not seen the doctor. My son was also fine with slight abrasion at the neck area.

There is an in car camera in my vehicle. The traffic police at scene already took the SD card for follow up. That's all.



**SINGAPORE
POLICE FORCE**



T/20201222/2089

3 of 4

Police Station Of Origin:

Bedok North N.P.C

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999

Report No. T/20201222/2089

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20201222/2089

4 of 4

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20201222/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 AHMAD BIN HASHIM

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SI YEO CHUN JIAN

Contact No.: 65476213

Signature Of Informant

Date/Time:

22/12/2020 16:27

Classification Of Case:

Authentication Stamp

NP168

POLICE FORCE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8619876B



Name

NGUAN KANG WEI, ALOYSIUS

阮 慷 伟

Race

CHINESE

Date of birth

21-07-1986

Country/Place of birth

SINGAPORE

Sex

M

S8619876B

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S8619876B

NGUAN KANG WEI, ALOYSIUS

Birth Date: 21 Jul 1986

Issue Date: 27 Jul 2018



002828895G

5883366



NRIC No. S8619876B



Date of issue

02-03-2018

Address

APT BLK 288C COMPASSVALE CRESCENT
#12-347
SINGAPORE 543288

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B	Motorcycles =< 200 cc	21 Apr 2005
Class 3	Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg	27 Jul 2018

NP 428A



Licence No: S8619876B

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)**Policy Query**

Policy No.

Date of Accident

Vehicle No.(For Motor)

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5120246965		GILSELLE WONG SZE QI	S8934581B	GPC	drive CLASSIC	SGT1243X	SGT1243X	12/12/2020	11/12/2021

ACCIDENT STATEMENT

ACCIDENT DATE: (22/12/20) (DD/MM/YYYY), TIME: (11:10) (HH:MM)

LOCATION: PIE

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SGT 1243X
b) INSURANCE COMPANY: IMC
c) POLICY NUMBER:
d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
e) MAKE & MODEL: Honda Fit 1.3 Auto.
f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
h) PURPOSE OF USING AT ACCIDENT TIME: Private Use
i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: CONTACT: 9650 2872
c) ADDRESS:

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: (MALE / FEMALE)
b) NRIC/FIN/PASSPORT: CONTACT: 9060 8524
c) ADDRESS:

- *d) DATE OF BIRTH: (/ /) (DD/MM/YYYY)
e) OCCUPATION: (INDOOR / OUTDOOR)
f) YEARS OF DRIVING EXPERIENCE:

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: spouse.

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION: Bedok North MPC

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SHA 877 L. MODEL:
b) DRIVER'S NAME:
c) NRIC/FIN/PASSPORT: CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: MODEL:
e) DRIVER'S NAME:
f) NRIC/FIN/PASSPORT: CONTACT:

email = aloysius.nguan@gmail.com

fax =

VIDEO = Yes. card with TP

ASSIGNMENT (IDAC)**By CSO- Nature of Accident:**

- 1) Vehicle hit Vehicle: 2) Vehicle hit ??
- a) Motorcar () a) Pedestrian ()
- b) M/cycle () b) Animal ()
- c) Bicycle ()
- 3) Vehicle hit Road Side Objects:
- a) Govrn. Property () b) Road Work Object ()
- (Eg: signboard, barrier, tree etc) c) Private Property ()
- 4) Vehicle drop into drain ()
- 5) Damage due to Act of God:
- a) Fallen Object () b) Flood ()
- c) Other, _____
- 6) Parked & Found Damaged:
- a) Vandalism () b) Hit by Moving Object ()
- 7) Theft Case
- a) Stolen () b) Damage found ()
- when recovered.
- 8) Fire
- a) Whilst driving () b) Parked ()
- 9) Accident date more than 24hrs ()

Remarks for internal information

Photos in P Drive
under my name.

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ()
- 2) SRS Light on ()
- 3) ABS Light on ()

By Assessor- 1) Vehicle Information

Veh No: SGT 1243X Yr Regn: 04 Aug 2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / MPV
/ Truck / Trailer or _____

Make & Model: Honda Fit 1.35 c.c _____

Colour: Black Transmission Type: Auto / Manual

Eng/No: _____ Sp. Reading: _____

C/No: GG 611 41 572 66

Gen. Cond: Good / Fair / Poor / Burnt or _____

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front / Rear

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

Parallel Import: Yes / No Towed-In: Yes / No

Repair Type: LS / I.B.I Towing Required: Yes / No

No of Repair Days: 10 Vehicle in Idac: Yes / No

D.O.I. 24-12-20 Time: 12pm

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

- a. Vehicle () b. Motorcycle () c. Bicycle () d. Pedestrian ()
- e. Animal () f. Govrn Object () g. Road Work Object ()
- h. Private Property () i. Drain () j. Road Kerb/Grass Verge ()

3) Vehicle does not seem damaged as a result of:

- a. Fallen Object () b. Flood () c. Vandalism () d. Fire ()
- e. Moving Object () f. Stolen () g. Stolen & Recovered ()

Time Started: _____

Time completed: _____

1) CSO _____

2) ASS _____

(4) Not Overlapped (NO)

Vehicle No: 56T1243X

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			?
1072	994011	Relay Box			?
1073	995053	Wiper Washer Tank			✓
1074	995052	Wiper Washer Tank Motor			?
1075	990159	Alternator Assy			?
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			?
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			?
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			?
1088	990950	Engine Mounting LH			?
1089	990952	Engine Mounting RH			?
1090	990951	Engine Mounting Rear			?
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			Repair
1093	991520	Frt RH Chassis Member			Repair
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			✓
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			1/4 glass window
1099	995148	Frt LH Fender Protector			1/4 glass window
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994023	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			✓
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			1/4 glass window
1108	991752	Frt RH Fender Protector			1/4 glass window
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			✓
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			✓
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		ECU			?
		Door Int Door			Repair
		Door sill plate garnish			