



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

TPVD Mitsubishi (SLZ5621X)

Date of Loss

20 December 2020

Time of Loss

16.30

Loss Description

XD3362E (INSD) C/W SLZ5621X

Comment

### Workshop Details

Total Rebate Amount

42239

Nett Loss Amount

\$33,761.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion \*

20



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

### Vehicle & Driver Details

Vehicle Registration#  
SLZ5621X

Registration State

SINGAPORE

Mileage

25258

CATEGORY

Manufacturing Year

POLICY INFORMAT...

ASSESSMENT INFO...

2018

CATEGORY

Make

Purchase Date

dd/mm/yyyy



Registration Date \*

09/05/2018



Age of Vehicle

2

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

CHUA YEONG KWANG

POST SURVEY INF...

POLICY INFORMAT... TPVD

ASSESSMENT INFO...

mitsubishi

CATEGORY Model

POLICY INFORMAT... Mitsubishi

ASSESSMENT INFO... outlander 2.0 cvt

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT...

ASSESSMENT INFO... GF7W0401585

CATEGORY Date of Birth

FNOL INFORMATI... 31 December 1899

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 121

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

---

CATEGORY

Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

4J11YA0284

---

CATEGORY

Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1998

---

CATEGORY

Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

0

---

CATEGORY

Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

76000

---

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

dd/mm/yyyy



CATEGORY Address

FNOL INFORMATI

FNOL INFORMATION...

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATION...

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATION...

Unknown

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATION...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATION...

S7119599F

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

23/12/2020



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

## Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Tyre Condition

Spare wheel

Front Tyre Size

225/55R18

Front left side

TOYO8mm

Front right side

TOYO8mm

Rear Tyre Size

225/55R18

Rear left side

TOYO7mm

Rear right side

TOYO7mm





SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes☐ No

Part Supplied by AXA

Yes

No

Save












Parts






Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR DOOR - RH	Bent	0	1278	No		10			1150.2	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR GLASS OUTER MOULDING - RH	Dented	0	185.5	No		10			166.95	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR LOCK - RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR DOOR OUTER HANDLE - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR DOOR REGULATOR GEAR - RH	Damaged	0	378.6	No		10			340.74	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR REGULATOR GEAR MOTOR - RH	Damaged	0	334.9	No		10			301.41	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR STICKER - RH	Necessary	0	85.5	No		10			76.95	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR TRIM BOARD - RH	Cracked	0	796	No		10			716.4	Reviewing
<input type="checkbox"/>		0	1		REAR DOOR WEATHERSTRIP - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR DOOR WEATHERSTRIP - RH	Dented	0	515	No		10			463.5	Reviewing
<input type="checkbox"/>		0	1		REAR FENDER - RH	Repair	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR FENDER GARNISH - RH	Dented	0	230.9	No		10			207.81	Reviewing
<input type="checkbox"/>		0	1		REAR KNUCKLE ARM - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR SHOCK ABSORBER - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR WHEEL BEARING - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR LOWER ARM - RH	Serviceable	0	0	No		10			0	Deny















Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
<input type="checkbox"/>		0		TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY	0	400	0	0	Reviewing		
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	0	420	0	0	Reviewing		
<input type="checkbox"/>		0		TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL	0	30	0	0	Reviewing		
<input type="checkbox"/>		0		TO REMOVE / RENEW REAR DOOR RH	0	60	0	0	Reviewing		
<input type="checkbox"/>		0		TO CHECK WIRING FUNCTION	0	20	0	0	Reviewing		
<input type="checkbox"/>		0		TO REMOVE / REPLACE UNDERCARRIAGE LABOUR					Deny		
<input type="checkbox"/>		0		WHEEL ALIGNMENT					Deny		



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing	0		
<input type="checkbox"/>		0	REAR WHEEL RIM - RH	Deny	0	SERVICEABLE	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount	\$4,353.96	
CATEGORY		ESTIMATE		ADJUSTED				
Spare Parts		\$0.00		\$3,423.96				
Labour		\$0.00		\$930.00				

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	3450		

Submit for Review