

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	UNITED OVERSEA	R	Ref:	CS3/UOI20014371/Gtd3e2		
	3 ANSON ROAD #2 SINGAPORE 07990	С	Date:	19/01/2021		
			C	Code:	UOI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMA 1012A	Veh. Inspected		SMP 3132U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	SMA1012A	Excess (\$)		0.00	
	Assign From	KATIE LEE	Assign Date		23/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.5	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	GP51339844	Colour		SILVER	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	185/60 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	185/60 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION					
5.	General Information					
	Accident Date	21/12/2020	Inspect Date / Ti	ime	24/12/2020 (05:15 PM)	
	Survey held at	vey held at BIFROST AUTO PTE LTD				
	8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
		Papart Raf No. CC2/	10100044074/044			

Report Ref No. CS3/UOI20014371/Gtd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor