

ASS. REC. BY:

REF:

CC3/1120014373/Riga3

2593

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGQ 72Uat Workshop m/s PERFORMANCEof 303, ALEXANDRA RDInsured: 111

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 203K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGQ 72U Yr Regn: 2020 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 318I ADT LEOHLS c.c. 1499 1998Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 0992 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA 7204060FK30558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modi: Nil / SRM / STD A/Rim or

Tyre Size: F: 225/42R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or .

Front

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 23/12/2020 D.O.I. 21/01/2021Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit = 125K

Date/Time, File Pass to?



: Prelt. Report

Days Of Repair: _____

1)



: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.R.A. (\$) _____



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Performance Motors Limited

Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

23 DEC 2020

Estimate No. : b1 57006
Date Estimated : 23/12/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Choy Liang Zhou (Xu Liangzhou)
Apt Blk 708 Hougang Avenue 2
#06-71

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 530708

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ72U	WBA72DY060FK30558	26/11/2020	318i	0

DESCRIPTION

VALUE

To replace front bumper, front left fender, bonnet, front wal
l including to knock out dente d area caused by the accident

3400 4,250.00

To respray front bumper, front left fender and bonnet

2989 3,321.00

To carry out body cavity preservation (2X)

200 238.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1x).

451? 531.00

To replace left headlight.

408 481.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct check for
proper function.

150 171.00

To check electrical wiring system at the front section
for proper function including adjustment of headlights.

150 171.00

Sundries

? 150.00

Total Labour 1: 9,323.00

DESCRIPTION

QTY

PRIC

VALUE

FRT LH SIDE PANEL BRACKET 1 ?

1

35.10

35.10

FRT LH SIDE PANEL ~~repair~~ 1 ?

1

811.55

811.55

HOOD 1 ?

1

1,568.15

1,568.15

FRT SHOCK ABSORBER 1 ?

1

57.30

57.30

FRT BOTTOM IMPACT ABSORBER 1 ?

1

57.30

57.30

FRT BUMPER CARRIER 1 ?

1

595.70

595.70

FRT BUMPER BOTTOM CARRIER 1 ?

1

327.65

327.65

LH VERTICAL CONNECTION 1 ?

1

16.85

16.85

RH VERTICAL CONNECTION 1 ?

1

16.85

16.85

LH RETAINING FRAME 1 ?

1

82.35

82.35

LH BUMPER TOP GUIDE 1 ?

1

19.50

19.50

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57006
Date Estimated : 23/12/2020
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGQ72U	WBA72DY060FK30558	26/11/2020	3181	0

DESCRIPTION	QTY	PRIC	VALUE
# GUIDE BUMPER LH BOTTOM ?	1	11.30	11.30
GRILLE AIR INLET MIDDLE (LINES) <i>see</i>	1	110.85	110.85
Grill, side, ?	1	79.20	79.20
BUMPER GUARD CENTRE ?	1	95.00	95.00
Air inlet finisher ?	1	67.85	67.85
# FRT BUMPER PANEL PRIMED (LIN <i>de</i>)	1	1,068.15	1,068.15
LH CRASH BOX ?	1	88.50	88.50
RH CRASH BOX ?	1	88.50	88.50
FRT GRILLE <i>ca</i>	1	220.80	220.80
EMBLEM GROMMET <i>see</i>	2	0.85	1.70
PLAQUE 82MM <i>see</i>	1	71.60	71.60
RIVET ?	6	0.50	3.00
# LH LOCK F HOOD ?	1	92.80	92.80
RH LOCK F HOOD ?	1	92.80	92.80
LOCK TOP PART ?	2	72.40	144.80
CONNECTION FRT TOP ?	1	223.45	223.45
FRONT CROSSLINK ?	1	222.75	222.75
V SUPPORT ?	1	112.75	112.75
# LH HEADLIGHT BRACKET ?	1	94.30	94.30
CONNECTION REAR TOP ?	1	151.30	151.30
# FRT LH WHEEL ARCH FRT SECTIO ?	1	120.65	120.65
# FRT LH BRAKE AIR DUCT ?	1	51.80	51.80
# LH WHEEL ARCH BRAKE AIR DUCT ?	1	48.55	48.55
AIR DUCT RADIATOR (4ZYL) ?	1	105.35	105.35
AIR DUCT WITH FLAP CONTROL ?	1	220.70	220.70
AIR DUCT WITH FLAP CONTROL TOP ?	1	285.90	285.90
LH WHEEL HOUSING BOTTOM COVER ?	1	67.95	67.95
# SEAL ENGINE BONNET FRT ?	1	39.85	39.85
# COVER OF CENTRE ENGINE COMPA ?	1	67.90	67.90
FRT LIGHT ELECTRONICS CONTROL UNIT ?	1	893.90	893.90
RH LED MODULE TURN IND./DAYTIME DRI ?	1	230.00	230.00
LH HEADLIGHT LED AHL <i>ca</i>	1	3,392.10	3,392.10
DECOUPLING RING ?	2	5.10	10.20
Ultrasonic sensor ?	2	381.90	763.80
Total Parts :			12,928.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time 21/01/2021 @ 1430 Excess S\$ _____
Surveyor's Name Paul Sign _____
Surveyor's Tel 9000068 Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail S-6 Day



Labour 1	:	9,323.00
Parts	:	12,928.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,557.59
Grand Total	:	23,808.94

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 23/12/2020 15:26 (SGT)
Date of Accident 23/12/2020 09:07 (SGT)
Exact Location of Accident Paya Lebar Rd, Singapore
Additional Location Information IN FRONT OF SHELL STATION (BESIDE JLN AFIFI)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGQ72U

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner CHOY LIANG ZHOU
NRIC No SXXXX259J
Email Address LIANG.ZHOU89@GMAIL.COM
Mobile Phone No (Phone) +65-98366565
Alternative Phone No +65-98366565

VEHICLE PARTICULARS

Manufacturer BMW
Model 318i
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company Axa
Type of Coverage Comprehensive
Fleet Policy No
Policy Number -
Cover Note Number -

DRIVER

Name of Driver CHOY LIANG ZHOU
NRIC No SXXXX259J
Date Of Birth 09/03/1989
Occupation Indoor

.....	06/02/2012
.....	8 YEARS AND 10 MONTHS
.....	Male
.....	(Phone) +65-98366565
.....	+65-98366565
.....	LIANG.ZHOU89@GMAIL.COM
.....	BLK 708 HOUGANG AVENUE 2 #06-71
.....	-
.....	530708
.....	Yes
.....	-
.....	No
.....	-
.....	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SHC2182J
Vehicle Manufacturer	Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	YUEN CHEE MENG
NRIC No	SXXXX654F
Contact Number	(Phone) +65-83632971
Address	237 TAMPINES ST 21 #11-551
Address complement	-
Postcode	520237

Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

India International
FRONT & RIGHT
-
-


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

23/12/2020 (11.00am)


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23rd December 2020 9.07am, I was driving straight on the second lane along Pagar Lela Road towards Guillemard Road.

When I just past the Shell Petrol Station, taxi SHC 2182J suddenly turned out of Jalan Afiti and collided onto my car front left portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

☒ Policyholder's Signature
Date & Time:

☒ Driver's Signature
(If driver is not the policyholder)
Date & Time:

23/12/2020 (11.00am)

☒ Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	259J

Vehicle No.:	SGQ72U
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2021
Vehicle Make:	B.M.W.
Vehicle Model:	318I ADPT LED HL SPORTLINE
Primary Colour:	Grey
Manufacturing Year:	2020
Engine No.:	F5563812B48B20A
Chassis No.:	WBA72DY060FK30558
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$41,367.00
Original Registration Date:	26 Nov 2020
First Registration Date:	26 Nov 2020
Transfer Count:	0
Actual ARF Paid:	\$49,914.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2030
PARF Rebate Amount:	\$37,435.00

COE Expiry Date:	25 Nov 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,101.00
COE Rebate Amount:	\$40,450.00
Total Rebate Amount:	\$77,885.00

The information contained herein is correct as at 22 Jan 2021

OK

Grey

Date Updated 08-Jan-2021

Submodel Pricing Information

318i Sport (A)

View Loan Breakdown

Current price	\$207,888
ⓘ Depreciation	\$18,300 /yr
ⓘ Down Payment	\$83,155 (Maximum 60% loan)
ⓘ Installment	\$1,774 /mth
COE quota premium	\$50,100 (Category B COE)
ⓘ Road tax	\$1,210 /yr
ⓘ OMV	\$41,346
ⓘ ARF	\$49,884
ⓘ VES	\$10,000 (Surcharge)
ⓘ Total basic cost	\$163,290
ⓘ Premium	27%
Previous recorded price	\$207,888
Highest recorded price	\$207,888 (past 6 mths)
Lowest recorded price	\$193,888 (past 6 mths)
» View full price history	

Date Updated 08-Jan-2021

New Car Dealer Details

Showrooms

Sime Darby Performance Centre
303 Alexandra Road Sime Darby Performance
Centre S(159941)
Tel: 63190100 / 31386272
Fax: 64747770