

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL	F	Ref:	CS/SMO20014423/Kqd3n2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	[Date:	29/07/2021	
			(Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 1564C	Veh. Inspected		GR 687R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003780/RUC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		24/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350 (M)	c.c		2488	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	JN1MC2E26Z0001874	Colour		SILVER	
	Odometer	192727 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15X8	BRIDGESTONE		9 mm	
	L/H Front Tyre	195 R15X8	BRIDGESTONE		9 mm	
	R/H Rear Tyre	195 R15X8	BRIDGESTONE		9 mm	
	L/H Rear Tyre	195 R15X8	BRIDGESTONE		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/12/2020	Inspection Date	!	24/12/2020	
	Survey held at	GUAN MOTOR WORKS				
		176 SIN MING DRIVE #02-03				
		SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
			1			