

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 7909X

at Workshop m/s Tandem 100m

of _____

Insured: GW 8/806

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$62k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LYA 43825

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR 7909X Yr Regn: 29/8/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496

Colour: Purple A/C: Insured / Std / NI / NA

Sp. Reading: 49605 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11221503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/12/20 D.O.I. 30/12/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/1/21 4/5 43825 confirmed with William (Red 745.68, 449)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 2

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2) 8/1/21-Typist

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : Merimen

Lump Sum H.B.I: (\$ 850)

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	384J
Vehicle Details	
Vehicle No.:	SLR7909X
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Purple
Manufacturing Year:	2017
Engine No.:	L15B4421507
Chassis No.:	RU11221503
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$22,375.00
Original Registration Date:	29 Aug 2017
First Registration Date:	29 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$13,325.00 6662
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Aug 2027
PARF Rebate Amount:	\$9,993.00
Intended COE Rebate Details	
COE Expiry Date:	28 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$33,832.00
Total Rebate Amount:	\$43,825.00

The information contained herein is correct as at 30 Dec 2020

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

BMW 320i Coupe Sunroof (COE Till 04/2029)



Low Depreciation, Sporty
 Looking, Maintenance Done. For
 More Info Whatsapp Me.
 Direct Owner StarAd

AutoInn
 An Inspiration For Car Buyers

click here to view
 our **PRISTINE USED CARS**
 at **GREAT PRICES**

Browse by Category

« Back (1 2 3 4) Next »

Sort by Date Posted

20 results/page

62 vehicles

Vezel

Advanced Search



Submit

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Vezel

Any

Any

2017

Any

Any

Any

Available

<

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/12/2020 10:33 (SGT)
Date of Accident	22/12/2020 14:10 (SGT)
Exact Location of Accident	Near 7 Jln Daud, Singapore 419553
Additional Location Information	Jalan Eunoss
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR7909X
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Tan Eng Seng
NRIC No	SXXXX384J
Email Address	engseng75@gmail.com
Mobile Phone No	(Phone) +65-98712335
Alternative Phone No	+65-98712335

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	NTUC
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5111352245-01
Cover Note Number	-

DRIVER

Name of Driver	Tan Eng Seng
NRIC No	SXXXX384J
Date Of Birth	10/04/1975
Occupation	Outdoor

Date Of Driving Pass	23/10/2003
Driving experience	17 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98712335
Alt. Phone Number	+65-98712335
Email Address	engseng75@gmail.com
Address	Block 424 Hougang Avenue 6
Address complement	#06-86
Postcode	530424
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Tan Hwee Hwee
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Refer to Sketch Plan

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW8180G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Van A: SLR7909X

Van B: GW8120A



Jalan
Famos

Exit
Arrow
PIE
Famos Line

Describe Circumstances of the Accident

On 22/12/2020 at about 1410 hrs, I was travelling along Jalan Eunos towards Eunos Link.

At the junction with PIE, the traffic light turned Green, I proceed straight in my lane (2nd lane from the left).

A van (B: GW 8180G) travelling on the 3rd lane veered to my lane, entering to the 2nd lane instead of his own lane. Thus, it hit onto the right rear corner of my vehicle (A: SLR 7909X).

The driver of GW 8180G failed to stop and I have to chase after him till Ubi Road.

No one was injured.

That's all!

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Jan
22/12/2020
@ 4:15 PM

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

[Signature]



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

CTP Insured's Veh No : GW8180G

Date of Accident : 22 December 2020

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Tan Eng Seng

Date : 23 December 2020

Rep: Marcus - Lkh

30/12/2020 10:00am

Estimate To Repair SLR7909X - Honda VEZEL 1.5X CVT

Chassis No : RU11221503

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>grazed</i>	\$ 532.10
02	1 pc	o/s rear bumper pad <i>cut</i>	\$ 195.00
03	1 pc	o/s rear wheel arch garnish <i>grazed</i>	\$ 195.00
04	1 set	rear mudflap <i>grazed</i>	\$ 185.00
			\$ 1,107.10
		Less 20 %	\$ 221.42
			\$ 885.68
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 80.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 250.00
03		Putty and spray painting of the affected portion.	\$ 380.00
			\$ 710.00
		Total	\$ 1,595.68

*not Authorized
20/12/20
20/12/20
20/12/20*

4/5 \$850

please submit to insurance

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*1045.80
202
836.64
1106.64
PR5*