

ASSIGNMENT

Insured Cost

TP / WS / TP RES / OD RES / EVA / INV / MV

Inspect Vehicle No:

Workshop m/s

Insured:

Policy No.

Claims No.

Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

DAC Accident Report:

Consistent? : Yes or No

SLA / PR Seen:

Consistent? : Yes or No

Est Repairs:

days

Res.: Yes or No

Sum Sum:

%

3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date

Person Contacted

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Date/Time, File Return to?

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp (\$

☐ Interview (\$

☐ Report (\$

☐ Other (\$

Survey Fee:

Transportation:

3 - 5000

1000

1000

1000

Vehicle

Type M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp Reading

Eng/No

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Modi Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

SMV 3775H

Regd 28 Sep 2020

CC 1998

A/C Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

BMW X3

Grey

7421

WBATS 72000.9C 71276

Good / Fair / Poor / Burnt

In order / Jammed / Leaked / Burnt or

In order / Jammed / Leaked / Burnt or

Nil / S/Rim / STD A/Rim or

F: 245/50R19

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal 8 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction

Date / Time

Action / Instruction