

ASS. REC. BY:

REF:

FC2/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 848k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 07 days

Res.: Yes or No

Lum Sum: 1.21 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBG 90010Yr Regn: 11, 17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: NIS Cabsta

c.c

2953Colour: Pilve

A/C:

Insured / Std / NI / NA

Sp. Reading: 172052

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: JN1SC2F2480860421Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 195R15X8R: 155R12X80D1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wentake

Front

Rear

R/Bal. 8 mmR/Bal. 44 mmL/Bal. 8 mmL/Bal. 44 mmD.O.A. 21/12/20D.O.I. 24/12/202

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/12Ah Kon said to get parts, 1.B.1

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

), F. P. H. S.

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

No EST0026215
Y Pte Ltd

Page 1 of 3
Your ref. TP-SHB 6608C MS FC
Job No. 71769
Our ref. 20.12.27
Payment
Date 22/12/2020

.....
Vehicle No GBG 9001C
Vehicle Model : Nissan Cabstar
Date on ... 21/12/2020

*Not Authorized
Resumey Bepain
Today*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
00	Pc	Front dashboard	<i>De/way</i> 2,305.80	10.00	2,075.22
00	Pc	Front windscreen	1,095.30	10.00	<i>CM</i> 985.77
00	Pc	Front windscreen moulding LH	71.10	10.00	<i>ne</i> 63.99
00	Pc	Front windscreen moulding RH	71.10	10.00	<i>ne</i> 63.99
00	Pc	Front wiper panel	525.30	10.00	<i>By</i> 472.77
00	Pc	Front wiper arm cover RH	10.00	10.00	<i>miy</i> 9.00
00	Pc	Front body panel	<i>mgem</i> 1,580.90	10.00	<i>Ry</i> 1,422.81
00	Pc	Front headlamp RH	427.10	10.00	384.39
00	Pc	Front headlamp lower garnish LH	81.30	10.00	<i>CM</i> 73.17
00	Pc	Front radiator grille	461.90	10.00	<i>miy</i> 415.71
00	Pc	Front radiator grille logo emblem	59.60	10.00	<i>miy</i> 53.64
00	Pc	Front Cabstar emblem	35.60	10.00	<i>ne</i> 32.04
00	Pc	Front bumper c/w bracket	1,155.10	10.00	<i>Ry</i> 1,039.59
00	Pc	Front radiator grille centre bracket	75.60	10.00	<i>Ry</i> 68.04
00	Pc	Air con cooling coil c/w heater blower	1,376.10	10.00	1,238.49
Special nett item:					

拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0026215
BUY Pte Ltd

Page: 2 of 3
Your ref.: TP-SHB 6608C MS FC
Job No.: 71769
Our ref.: 20.12.27
Payment
Date: 22/12/2020

tn

Vehicle No: GBG 9001C
Vehicle Model : Nissan Cabstar
Accident on ...: 21/12/2020

Today

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Air con blower	587.20		587.20
1.00	Pc	Air con pipe (condenser to coolingn coil)	219.50		219.50
1.00	Pc	Front wiper linkage	172.90		172.90
1.00	Pc	IU bracket	15.00		15.00
		Labour & Misc:			
1.00		Towing fee	70.00		70.00
1.00		To repair and supply main harness socket	80.00		80.00
1.00		To remove and renew front windscreen	140.00		140.00
1.00		To supply sealant	40.00		40.00
1.00		To dismantle + renew dashboard	200.00		200.00
1.00		To dismantle + renew air con cooling coil, heater blower, air con pipe and refill gas	220.00		220.00

AKK Auto Consultants
The Repairs of the following:
• To replace broken/defective parts
• To replace damaged parts
• Parts provided subject to inspection
• Third party survey
• No illegal modification is allowed
• Supplementary work is subject to final approval by the insurance company
Acknowledged by Reparer
Signature:
Date:

公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。外，还有先进的 SAICO Deluxe 喷漆烘炉。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support ally system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

ST. No EST0026215
BUY Pte Ltd

Page 3 of 3
Your ref. TP-SHB 6608C MS FC
Job No. 71769
Our ref. 20.12.27
Payment (GST)
Date (GST) 22/12/2020
New Bridge Rd, Singapore
Singapore

Vehicle No GBG 9001C
Vehicle Model : Nissan Cabstar
Accident on ... 21/12/2020

DETAILS OF OWN VEHICLE

GBG9001C

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To straighten front body including cutting and welding, to knock dents on front door pillar LH & RH and renew of parts	650.00		650.00 <i>600</i>
1.00		To spray paint	500.00		500.00 <i>480</i>

BUY Pte Ltd
200000783K
sit.hidayah@debuygroup.com.sg
(Phone) +65-9177771
(Office) +65-67770633

VEHICLE PARTICULARS

Manufacturer
Model
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle?
Vehicle Category

Nissan

Cabstar

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total 11,293.22
GST 7.00% 790.53
Total S\$ 12,083.75

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
还有先进的 SAICO Deluxe 喷漆烘炉。
Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
ly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
lux oven heater for re-spraying all motor vehicles."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/12/2020 17:09 (SGT)
Date of Accident	21/12/2020 03:10 (SGT)
Exact Location of Accident	New Bridge Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG9001C
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	EBUY Pte Ltd
Company Reg No	2XXXXX783K
Email Address	siti.hidayah@ebuygroup.com.sg
Mobile Phone No	(Phone) +65-91777716
Alternative Phone No	(Office) +65-67770633

VEHICLE PARTICULARS	
Manufacturer	Nissan
Model	Cabstar
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	EQ
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMCPHQ20-003637
Cover Note Number	-

DRIVER	
Name of Driver	Pitchaipillai Veerakumar
Passport No/FIN	GXXXX434T
Date Of Birth	28/08/1995
Occupation	Outdoor

Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

18/08/2018
2 YEARS AND 4 MONTHS
Male
(Phone) +65-94688301
-
veeracivil331@gmail.com
c/o 32 Quality Road
-
618804
No
Employee
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - U-Turn
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB6608C
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Taxi
Name of Driver Lim Siang Soon
NRIC No SXXXX893A
Contact Number (Phone) +65-97431293
Address -
Address complement -
Postcode -

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time
21 DEC 2020

Driver's Signature (If driver is not the policyholder) / Date & Time
21 DEC 2020

Witnessed by Reporting Centre Personnel
Jenny Lim

Sketch Plan



A - GBB 9001C
B = SHB 6608C

Describe Circumstances of the Accident

The incident happened this morning 3.10 am (21/12/2020).

I was driving my company lorry no. GBG 9001C along New Bridge Road. I was going straight and a taxi no. SHB 6608C from my right making a u-turn and both vehicle collided. No one was injured.

P. W. H.

Declaration

We declare the foregoing particulars are true in every respect.



P. W. H.

Policyholder's Signature / Date & Time
21 DEC 2020

P. W. H.

Driver's Signature (If driver is not the policyholder) / Date & Time
21 DEC 2020

Jenny Lim

Witnessed by Reporting Centre Personnel
Jenny Lim