

APP. REC. BY: FormREF: CS/CTI20014464/R1vd3

3412

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SBL 91Aat Workshop m/s TRANSEUROKASof JIA, TANJONG PENJURUInsured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

before 3pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 87K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SBL 91AYr Regn: 2019 / APRType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA CX-3 2.0 AT DELUXE c.c. 1998Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 24660

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DK2W7AK6416247Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50 R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

☒ TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/12/2020D.O.I. 24/12/2020Survey held at TRANSEUROKASDes. of Damages: Frt ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 34k

Date/Time, File Pass to?



: Prel. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

1)



: Final Report

Date/Time, File Return to?

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$ _____)

S + RS. \$ _____

☐ : Interview (\$ _____)

Photos

☐ : Tech. Invs (\$ _____)

Others

☐ : Weekend (\$ _____)

TOTAL

Rep. Format: _____

Lump Sum / I.B.F. (\$) _____



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Tong Poh Kwang ADDRESS : 58 Sengkang East Way Singapore 548597 TEL : 93841668		WIP : 24865 EXCESS : DATE: 21-Dec-20			
VEH NO :	SBL91A	DATE IN :		CONTACT PERSON :	Jess 63957874		
CHASSIS NO :	JM6DK2W7AK0416247	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	CX-3	DATE REG.:	30-Apr-19	POLICY NO. :			
<u>NATURE OF WORKS</u>							
<u>Parts Description</u>							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	REAR BUMPER <i>be /</i>	MDHYF-50-22XABB	1	✓			1,088.40
2	RETAINER LHS <i>X</i>	MD10J-50-2J1B	1	X			24.60
3	RETAINER RHS <i>X</i>	MD10J-50-2H1B	1	X			24.60
4	BRACKET CENTER <i>cm /</i>	MD10J-50-271	2	✓			52.20
5	PIN LOCATOR, REAR BUMPER <i>X</i>	MD10J-50-1K5	1	X			3.90
6	PAD, REAR BUMPER <i>ne /</i>	MBR55-56-994	2	✓			15.20
7	TAPE PROTECTOR, REAR BUMPER <i>ne /</i>	MG043-62-864A	2	✓			7.00
8	FASTENER, REAR BUMPER <i>ne /</i>	MB45A-56-146A	10	5 ✓			30.00
9	RETAINER CENTER, SENSOR <i>ne /</i>	MGHP9-67-UC5	2	✓			22.60
10	SENSOR CENTER, ULTRASONIC <i>X</i>	MGMC8-67-UC1	2	X			401.00
11	PAD PROTECTOR, REAR BUMPER <i>ne -</i>	MG001-67-061	2	✓			15.60
12	CORD SHORT, SENSOR <i>X</i>	MD24H-67-SH0	1	X			119.70
13	GUARD CENTER, REAR BUMPER <i>X</i>	MD10J-50-371	1	X			17.10
14	COVER UNDER, REAR BUMPER <i>X</i>	MD10J-50-C51	1	X			42.60
15	REFLECTOR LHS, REAR BUMPER <i>cm /</i>	MD10E-51-5M0A	1	✓			144.90
16	REFLECTOR RHS, REAR BUMPER <i>X</i>	MD10E-51-5L0	1	X			144.90
17	REAR REINFORCEMENT <i>bt /</i>	MDB2P-50-260A	1	✓			362.80
18	BRACKET LHS, BLIND SPOT <i>cm /</i>	MDB2S-67-Z4X	1	✓			86.80
19	BRACKET RHS, BLIND SPOT <i>X</i>	MDB2R-67-Z4X	1	X			86.80
20	MODULE LHS, BLIND SPOT <i>?</i>	MD24H-67-Y90E	1	?			1,347.50
21	MODULE RHS, BLIND SPOT <i>?</i>	MD24H-67-Y80E	1	?			1,347.50
22	ANTENNA <i>X</i>	MKD47-67-6NXA	1	X			111.10
23	CLIP, ANTENNA <i>X</i>	MKD45-67-6NYA	1	X			2.70
24	TAILGATE <i>bae /</i>	MDKY0-62-02XC	1	✓			1,089.90
25	RUBBER HOLE, TAILGATE <i>cm /</i>	MD10E-62-866A	1	✓			16.20
26	COVER HOLE, TAILGATE <i>ne /</i>	MD24H-62-866	4	✓			10.00
27	SWITCH OPEN, TAILGATE <i>?</i>	MD10E-62-4B0B	1	?			86.80
28	SWITCH, TAILGATE <i>?</i>	MBHN1-56-8D0B	1	?			109.20
29	LOCK, TAILGATE <i>?</i>	MDM0P-62-310	1	?			212.30
30	FASTENER, TAILGATE <i>ne /</i>	MEG21-51-146	3	✓			18.60

31	GROMMET, TAILGATE <i>nee ✓</i>	MBF67-51-261	2	✓			4.80
32	CLIP, TAILGATE <i>nee ✓</i>	MEG21-51-SJ3	2	✓			11.40
33	CLIP, TAILGATE <i>nee ✓</i>	MB01A-51-958	3	✓			10.80
34	TRIM, TAILGATE <i>cut ✓</i>	MDM0P-68-960	1	✓			232.80
35	RECESS, TAILGATE <i>X</i>	MGJ6A-68-966 02	1	X			23.10
36	TRIM LHS, TAILGATE <i>cut ✓</i>	MD10E-68-950	1	✓			25.20
37	TRIM RHS, TAILGATE <i>cut ✓</i>	MD10E-68-940	1	✓			25.20
38	TRIM TOP, TAILGATE <i>X</i>	MDM0P-68-930	1	X			68.50
39	WEATHERSTRIP, TAILGATE <i>cut ✓</i>	MD10E-62-761A	1	✓			167.00
40	FASTENER, TAILGATE <i>X</i>	MGJ21-68-885B02	5	X			15.00
41	REAR WINDSCREEN <i>bn ✓</i>	MDD1V-63-930	1	✓			797.50
42	FASTENER, REAR WINDSCREEN <i>nee ✓</i>	MD204-50-896A	2	✓			5.60
43	TAILLAMP LHS <i>sc ✓</i>	MDM4N-51-160A	1	✓			1,910.50
44	TAILLAMP RHS <i>X</i>	MDM4N-51-150A	1	X			1,910.50
45	LAMP LHS, TAILGATE <i>sc ✓</i>	MDM4N-51-3G0A	1	✓			955.10
46	LAMP RHS, TAILGATE <i>?</i>	MDM4N-51-3F0A	1	?			955.10
47	GASKET LHS, TAILGATE-LAMP <i>X</i>	MDB3D-51-3J8	1	X			41.30
48	GASKET LHS, TAILGATE-LAMP <i>X</i>	MDB3D-51-3H8	1	X			41.30
49	BRACKET LHS, TAILGATE-LAMP <i>sc ✓</i>	MDB2R-51-3JXA	1	✓			39.00
50	BRACKET RHS, TAILGATE-LAMP <i>X</i>	MDB2R-51-3HXA	1	X			39.00
51	MASCOT, REAR <i>nee ✓</i>	MD11B-51-730	1	✓			54.30
52	ORNAMENT, CX-3 <i>nee ✓</i>	MD10J-51-721	1	✓			55.70
53	ORNAMENT, SKYACTIV <i>nee ✓</i>	MD10J-51-771A	1	✓			56.60
54	REAR END PANEL <i>st ✓</i>	MD1YE-70-75ZC	1	✓			485.50
55	BRACKET LHS, GARGINSH-FENDER <i>X</i>	MD10E-51-U40B	1	X			30.90
56	BRACKET RHS, GARGINSH-FENDER <i>X</i>	MD10E-51-U30B	1	X			30.90
57	GARNISH LHS, REAR FENDER <i>X</i>	MD10E-51-W60C	1	X			70.30
58	GARNISH RHS, REAR FENDER <i>X</i>	MD10E-51-W50C	1	X			70.30
59	FASTENER, GARNISH <i>X</i>	MKD51-51-W24	6	X			48.00
60	FASTENER, GARNISH <i>X</i>	MKD53-51-W24	4	X			16.40
61	TRIM, END PANEL <i>cut ✓</i>	MDM0P-68-89X 02	1	✓			86.80
62	BEZEL, TRIM <i>MCS ✓</i>	MD10E-68-894 02	1	✓			4.70
63	LAMP LHS, LICENCE <i>?</i>	MB45A-51-2L0A	1	?			74.70
64	LAMP RHS, LICENCE <i>?</i>	MB45A-51-270B	1	?			74.70
65	CAMERA-BACK <i>sc ✓</i>	MD24M-67-RC0	1	✓			793.80
66	SILENCER <i>?</i>	MPEG8-40-100A	1	?			1,349.30
67	HANGER, SILENCER <i>?</i>	MBP47-40-061A	4	?			140.00
68	CONVERTER <i>?</i>	MPEG8-20-55X	1	?			1,278.70
69	HANGER, CONVERTER <i>?</i>	MPE70-40-061	2	?			57.00
70	HANGER, CONVERTER <i>?</i>	MKL16-40-061	1	?			28.40
71	GASKET, EXHAUST <i>?</i>	MP549-40-305	2	?			30.80
TOTAL PARTS							19,159.00
TOTAL PARTS COST							19,159.00
SUPPLEMENTARY							

17	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)	150	250.00
18	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00
19	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. <i>invoice?</i>	NETT	100.00 ✓
20	MZ-BR-SUNDRI	SUNDRIES.	NETT	20 100.00 ✓

TOTAL LABOUR	-	14,730.00
TOTAL PARTS	-	19,159.00
TOTAL	-	33,889.00
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A		
2	#N/A		

TOTAL LABOUR	-	-
TOTAL PARTS	-	-
TOTAL	-	-
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Rasul
Hp 90010068
9 days

24/12/2020 @ 1400

Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/12/2020 14:01 (SGT)
Date of Accident	18/12/2020 17:22 (SGT)
Exact Location of Accident	Yishun, Singapore
Additional Location Information	YISHUN AVE 1 TOWARDS AVE 8 JUNCTION OF YISHUN AVE 2
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SBL91A

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Mr Tong Poh Kwang
NRIC No	SXXXX341I
Email Address	gtr9122@gmail.com
Mobile Phone No	(Phone) +65-93841668
Alternative Phone No	+65-93841668

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	Cx-3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	KANG LENG LENG (KANG LINGLING)
NRIC No	SXXXX423J
Date Of Birth	18/02/1973
Occupation	Indoor

Date Of Driving Pass	10/03/1998
Driving experience	22 YEARS AND 9 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98765999
Alt. Phone Number	-
Email Address	adelinel00@hotmail.com
Address	58 Sengkang East Way
Address complement	-
Postcode	548597
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Tong Siu Yee
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

!! DETAILS OF OTHER VEHICLE PROPERTY !!

Vehicle Registration Number	GBK385H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	RAMALINGAM VENGATESAN
Passport No/FIN	GXXXX291W

Contact Number (Phone) +65-97608941
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Date & Time of Signature
Name:
NRIC/ID No.:


SKETCH PLAN


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 18/12/20, I was on the 3rd lane @ Yishun Ave 1 toward Ave 8, junction of Yishun Ave 2. When I was about to move to cross the junction, traffic light started to change from green to amber, I stopped my car immediately. ~~Suddenly~~, The next moment my car was being hit from behind.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Party/Personnel's Signature
Name:
NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	341I

Vehicle No.:	SBL91A
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Dec 2020
Vehicle Make:	MAZDA
Vehicle Model:	CX-3 2.0 AT DELUXE 2WD
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	PE31338028
Chassis No.:	JM6DK2W7AK0416247
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$21,161.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$21,626.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2029
PARF Rebate Amount:	\$16,219.00

COE Expiry Date:	29 Apr 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,209.00
COE Rebate Amount:	\$35,978.00
Total Rebate Amount:	\$52,197.00

The information contained herein is correct as at 24 Dec 2020

OK

Red

Mazda CX-3 2.0A Deluxe

Overview Financial Accessories Similar Research Photos Map

CREATIVE
AUTO



Price	\$84,888		
Depreciation ⓘ	\$9,160 /yr View models with similar depre	Reg Date	21-Jan-2019 (8yrs 27days COE left)
Mileage	49,988 km (26k /yr)	Manufactured ⓘ	2018
Road Tax ⓘ	\$1,210 /yr	Transmission	Auto
Dereg Value ⓘ	\$40,334 as of today (change)	OMV ⓘ	\$21,293
COE ⓘ	\$30,959	ARF ⓘ	\$21,811
Engine Cap	1,998 cc	Power	115.0 kW (154 bhp)
Curb Weight ⓘ	1,290 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		

Features

2.0L DOHC 16V SkyActiv-G Engine, 6 Speed Auto, Traction/Cruise Control, I-Stop, ABS, SRS, HUD, LED DRL, Keyless Entry/Start/Stop, Electric Memory Seat View specs of the Mazda CX-3 (2018-2020)

