



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM20014487/T1ga3q2 Date: 17/06/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SME 5809X	Veh. Inspected	SMG 620U	
Policy No.	GA551622	Coverage (\$)	0.00	
Claim No.	S0M02ZDX	Excess (\$)	0.00	
Assign From		Assign Date	24/12/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN POLO	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WVWZZZAWZKU024818	Colour	WHITE	
Odometer	22561 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	FALKEN	6 mm	
L/H Front Tyre	195/55 R16	FALKEN	6 mm	
R/H Rear Tyre	195/55 R16	FALKEN	6 mm	
L/H Rear Tyre	195/55 R16	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/12/2020	Inspection Date	29/12/2020	
Survey held at	RICO 60 AUTO SERVICES PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	