

ASS. REC. BY:

REF:

CS/SM0200/4517/Rtd/3

5336

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLJ 3892Cat Workshop m/s PERFORMANCEof 303, ALEXANDRA RDInsured: SOMPO

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: 500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 73K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLJ 3892C Yr Regn: 2016 / DECType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 116D HATCH. c.c. 1496Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 63143 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA IV 72090V 725 205Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: CONTINENTAL

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 24/12/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 29/12/2020PERFORMANCE

Date / Time Action / Instruction

Repair Invt 33K

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

Rep. Format: \_\_\_\_\_

Lump Sum / L.B. (\$) \_\_\_\_\_

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Page No. : 1 of 5

Estimate No. : b1 57021  
Date Estimated : 24/12/2020  
Prepared By : Chua Kee Sin

### - ESTIMATE REPAIR FOR -

Ong Pang Siong  
17 Anchorvale Crescent  
#02-13

Singapore 544652

### - ACCOUNT - 509

Sompo Insurance Singapore Pte Ltd  
50 Raffles Place  
#03-03 Singapore Land Tower  
Singapore 048623

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ3892C	WBA1V72090V725205	08/12/2016	116d	0

### DESCRIPTION

Replace front bonnet, front bumper include remove attachment etc and carryout repair on accident area

1700 ~~2,580.00~~

Painting front bonnet and front bumper, fender

2102 ~~2,336.00~~

To check electrical wiring system at the front section for proper function including adjustment of headlights.

150 ~~177.00~~

To replace right headlight.

408 ~~481.00~~

To supply front emboss number plate.

X 83.00

To carry out body cavity preservation. (Per panel).

100 ~~118.00~~

Sundries

? 150.00

Total Labour 1: 5,895.00

### DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BONNET <del>51</del>	1	1,178.70	1,178.70
FRT BUMPER TOP MOUNT ?	1	380.00	380.00
FRT BUMPER LH INSERT ?	1	25.70	25.70
FRT BUMPER RH INSERT ?	1	25.70	25.70
IMPACT ABSORBER TOP ?	1	46.95	46.95
GRILLE MIDDLE BOTTOM ?	1	125.70	125.70
FRT BUMPER RH INSERT ?	1	60.45	60.45
FRONT BUMPER TOWING COVER PRIMED X	1	39.15	39.15
FRT BUMPER PANEL PRIMED repair	1	829.65	829.65
LH ROOF MOULDING PRIMED X	1	182.10	182.10
RH GRILLE (BASIS) cm	1	91.10	91.10
EMBLEM GROMMETS	2	0.85	1.70
GAS STRUT HOOD X	2	118.70	237.40
RH LOWER PART OF HOOK LOCK X	1	88.40	88.40
STOP BUFFER X	2	12.65	25.30

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 57021  
Date Estimated : 24/12/2020  
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLJ3892C	WBA1V72090V725205	08/12/2016	116d	0

DESCRIPTION	QTY	PRIC	VALUE
RH SUPPORT ?	1	132.15	132.15
FRT BUMPER LOWER MOUNT ?	1	134.45	134.45
ADJUSTER ?	1	6.35	6.35
FRONT ENGINE HOOD SEALING ?	1	39.05	39.05
PLAQUE 82MM X	1	71.60	71.60
RH HEADLIGHT LED TECHNOLOGY cm /	1	2,145.20	2,145.20
DECOUPLING RING PDC TORQUE CONVERTE m /	4	5.10	20.40
PDC SENSOR ALPINWEISS (300) ? X	4	370.00	1,480.00

Total Parts : 7,367.20

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 29/12/2020 @ 0946 Excess S\$ 500

Surveyor's Name Rahul Sign \_\_\_\_\_

Surveyor's Tel 90010068 Authorised Yes (No) Revert

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,895.00
Parts	:	7,367.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	928.35
Grand Total	:	14,190.55

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE \*\*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	24/12/2020 11:13 (SGT)
Date of Accident	24/12/2020 08:04 (SGT)
Exact Location of Accident	Bedok Reservoir, Singapore
Additional Location Information	TRAFFIC LIGHT
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SLJ3892C

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ONG PANG SIONG
NRIC No	SXXXX533E
Email Address	HARDBOXES@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97433551
Alternative Phone No	+65-97433551

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	116d
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

#### INSURANCE COMPANY

Name of Insurance Company	Sompo
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D20MTPV01016209
Cover Note Number	-

#### DRIVER

Name of Driver	ONG PANG SIONG
NRIC No	SXXXX533E
Date Of Birth	12/07/1969
Occupation	Indoor

07/07/1988  
32 YEARS AND 5 MONTHS  
Male  
(Phone) +65-97433551  
+65-97433551  
HARDBOXES@HOTMAIL.COM  
17 ANCHORVALE CRESCENT #02-13

544652

Yes

No

Collision - Head to Rear

Clear

Dry

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....  
Weather Conditions .....  
Road Surface .....

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? ..... No  
Number of vehicles involved in the accident ..... 2  
Was anybody injured in the Accident? ..... No  
Was any injured conveyed to hospital by ambulance? ..... -  
Was any other material or property damaged? ..... Yes  
Number of Passengers (Including Driver) ..... 1  
Has the driver been approached by unknown person(s)  
soliciting/offering accident claims assistance? ..... No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
Was notice of intended Prosecution given? ..... No  
If yes, against whom? .....

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACH.

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... Yes  
Was there any video captured by Car Camera? ..... Yes  
Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number ..... GBA5701Z  
Vehicle Manufacturer ..... -  
Vehicle Model ..... -  
Vehicle Variant ..... -  
Vehicle Colour ..... -  
Vehicle Category ..... Commercial vehicle  
Name of Driver ..... WEE SIN CHAI  
NRIC No ..... SXXXX779F  
Contact Number ..... (Phone) +65-94559749  
Address ..... -  
Address complement ..... -  
Postcode .....

Company Name .....  
Damage .....  
Property damaged in accident .....  
Passenger (Including Driver) .....

-  
REAR & RIGHT  
-  
-




## SKETCH PLAN


### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24th DEC 2020, I was stopping at the red light (traffic light). Suddenly the front lorry rolled backwards and knocked into my car.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

24/12/2020  
@ 1040hr



**> Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	533E

Vehicle No.:	SLJ3892C
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Dec 2020
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCH DSC LED
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	33589706B37D15A
Chassis No.:	WBA1V72090V725205
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,555.00
Original Registration Date:	08 Dec 2016
First Registration Date:	08 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$11,377.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Dec 2026
PARF Rebate Amount:	\$8,532.00

COE Expiry Date:	07 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,668.00
COE Rebate Amount:	\$31,275.00
Total Rebate Amount:	\$39,807.00

The information contained herein is correct as at 29 Dec 2020

OK

White



Merimen e-Claims



Used 2016 BMW 1 Series 116d for



PARF/COE P

armart.com/used\_cars/info.php?ID=948644&amp;DL=1043

## ► BMW 1 Series 116d

Overview

Financial

Accessories

Similar

Research

Photos

Map



Ho Bee Group

HIN LUNG AUTO PTE LTD



Price	\$73,800	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation ?	\$11,440 /yr View models with similar depre	Reg Date	12-Dec-2016 (5yrs 11mths 12days COE left)
Mileage	76,000 km (18.8k /yr)	Manufactured ?	2016
Road Tax ?	\$1,082 /yr	Transmission	Auto
Dereg Value ?	\$37,109 as of today (change)	OMV ?	\$24,555
COE ?	\$48,000	ARF ?	\$11,377
Engine Cap	1,496 cc	Power	85.0 kW (113 bhp)
Curb Weight ?	1,350 kg	No. of Owners ?	1
Type of Vehicle	Hatchback		

## Features

Powerful BMW 1.5L Diesel TwinPower Turbo Delivered 113Bhp And 270Nm Torque, 8 Speed Gearbox, Auto  
St Driving Mode, Rear Wheel Drive. View specs of the BMW 1 Series Hatchback Diesel (2015-

