



AIG - OD (REVERT)
SURVEY: 28/12/20
LKK - STEVE

VEHICLE NO : SFA4832 M

MODEL : KIA/CERATO 1.6 A SX

WIP : 26326

Material	:	\$	<u>1,084.80</u>
Labour	:	\$	<u>1,920.00</u>
Sub-Total	:	\$	<u>3,004.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>3,004.80</u>
GST 7%	:	\$	<u>210.34</u>
Grand Total	:	\$	<u>3,215.14</u>
Finalise By/Date : <u>Larry on 13/01/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 3 days (wk end & p.h.)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10928/LEE MUN CHUNG(LI MINZHONG) Reg No/Reg Date SFA4832M*ECB1/ 20/08/2019 Date In/Mileage 29/12/2020/ 14926 Chassis/Package KNAF3416MK5049787 /KC17 Engine No G4FGKH744191 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK
29/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	13/01/2021/ 10:08	BLD	884 / Lauro Songcuan	26326

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON RH FRONT FENDER, RH FRONT DOOR				600.00 ✓
E PNT98000 SPRAY PAINT RH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTIONS				960.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED PORTIONS				40.00 ✓
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB LABOUR TO TRANSFER RH FRONT SPORT RIM WITH VALVE SUPPLY				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST → <i>Supp</i> USING HI-SCAN PRO TEST				120.00 ✗
X PANEL-FENDER,RH ✓	1.00	430.00	20.00	344.00 ✓
X WHEEL ASSY-ALUMINIUM ✓	1.00	926.00	20.00	740.80 ✓
Z TEXT OD CLAIM - AIG DOA: 26.12.2020 A SURVEY: STEVE (LKK) 28.12.20 04 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,084.80		Nett	3,004.80
Labour	1,830.00	7% GST on	3004.80	210.34
Standard Menu	0.00			
Specialist Job	30.00			
Diagnostics Job	0.00		Total Payable	3,215.14
Sundry/Others	60.00			
Total(w/o GST)	3,004.80			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SFA 4832 M

	<u>Labour</u>	<u>Cost \$</u>
1	To Carry Out Diagnostic Check Using Hi-Scan Pro Test	120.00
	7% GST	8.40
	Total	128.40

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SEA 4832MWIP: 26326

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	To carry out damage to the chassis	? / SUPP			
2		? / SUPP			
3		? / SUPP			
4		? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	4/1/21	SPR
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: Cerato 1.6 SXSURVEYOR: Steve O LK

Work Order: R001291
 License: sfa 4832 m
 Technician: 810119
 Mileage: 14926
 Date: 29.12.20 18:25

KIA CERATO 1.6 2019

Front : Left

Actual	Before	Specified Range
-0°17'	-0°18'	-0°53' 0°07'
4°22'	4°22'	4°00' 5°00'
0°01'	0°13'	-0°03' 0°09'
12°51'	12°52'	13°30' 14°30'
12°34'	12°34'	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°47'	-0°49'	-0°53' 0°07'
4°57'	4°57'	4°00' 5°00'
0°03'	0°19'	-0°03' 0°09'
10°54'	10°56'	13°30' 14°30'
10°07'	10°07'	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°30'	0°31'	
-0°35'	-0°35'	
1°57'	1°56'	
0°04'	0°32'	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°02'	-1°02'	-1°42' -0°42'
0°04'	0°04'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°31'	-1°31'	-1°42' -0°42'
0°07'	0°06'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°28'	0°29'	
0°10'	0°10'	-0°04' 0°32'
-0°02'	-0°01'	

* This value is not within specification. Tire wear, handling and safety problems may result.

Work Order: R001291
 License: sfa 4832 m
 Technician: 810119
 Mileage: 14926
 Date: 29.12.20 18:25

KIA CERATO 1.6 2019

Front : Left

Actual	Before	Specified Range
-0°17'	-0°18'	-0°53' 0°07'
4°22'	4°22'	4°00' 5°00'
0°01'	0°13'	-0°03' 0°09'
12°51'*	12°52'*	13°30' 14°30'
12°34'*	12°34'*	12°37' 14°37'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°47'	-0°49'	-0°53' 0°07'
4°57'	4°57'	4°00' 5°00'
0°03'	0°19'	-0°03' 0°09'
10°54'*	10°56'*	13°30' 14°30'
10°07'*	10°07'*	12°37' 14°37'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°30'	0°31'	
-0°35'	-0°35'	
1°57'	1°56'	
0°04'	0°32'*	-0°06' 0°18'

Rear : Left

Actual	Before	Specified Range
-1°02'	-1°02'	-1°42' -0°42'
0°04'	0°04'	-0°02' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°31'	-1°31'	-1°42' -0°42'
0°06'	0°06'	-0°02' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°28'	0°29'	
0°10'	0°10'	-0°04' 0°32'
-0°01'	-0°01'	

* This value is not within specification. Tire wear, handling and safety problems may result.

HOME Online  CERATO/FORTE../2019/G 1.6 MPI.. VCI  

 **Fault Code Searching**

Rescan

Erase All DTC

Go to DTC

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
		No Current DTC	

S/W Ver.

M-E-K-01-00-0236

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0177

OS Ver.

Android 9

HOME
 Online

CERATO/FORTE../2019/G 1.6 MPI..

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

ICU
 CLU
 WPC

12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
		No Current DTC	

S/W Ver.	M-E-K-01-00-0236	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0177	OS Ver.	Android 9