

ASS. REC. BY:

REF:

AIG

## ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFA 4832M

Yr Regn:

20/8/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c 1591

Colour:

Red

A/C: Insured / Std / NI / N

Sp. Reading

14868

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

KNA F 3416 MK 5049787

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/R/m / STD A/R/m or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXA

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

26/12/20

D.O.I.

28/12/20

Survey held at

Cycle &amp; Carriage

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt R.H.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-78K

Date/Time, File, Pass to?

☐

Prell. Report

☐

Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (%)

☐

Weekend (\$

Photos

Others

TOTAL

App. Formed:

App. Sum / L.R. / C.R.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10928/LEE MUN CHUNG(LI MINZHONG) Reg No/Reg Date SFA4832M*ECB1/ 20/08/201 Date In/Mileage / 0 Chassis No KNAF3416MK5049787 Engine No G4FGKH744191 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/12/2020/ 10:05	QUD	247 / DonBong	26326

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH FRONT FENDER, RH FRONT DOOR, REPAIR RH SIDE SILL PANEL	1			600 1200.00
E PNT88000 TRANSFER RH FRONT DOOR GLASS, DOOR TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	1/2			X 120.00
E PNT98000 PAINT WORK SPRAY RH FRONT FENDER, RH FRONT DOOR, RH SIDE SILL PANEL AND AFFECTED PORTION CLEAR COAT CR5	480' x 2 (CR5 colour)			960 1440.00
M SUNDRY APPLY BODY SEALANT				X 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00
M SUNDRY PERFORM RUST PREVENTION				40 80.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00
A 20000001 RENEW FRONT UNDERCARRIAGE				? 400.00
M SUNDRY LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING				30.00
M SUNDRY SUNDRIES				20 50.00
M PANEL-FENDER,RH	1.00	430.00	20.00	344.00
M INSULATOR-FENDER RH	1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR,RH	1.00	1277.00	20.00	1021.60
M BLACK TAPE-FR DR RR,RH	1.00	13.00	20.00	10.40
M LAMP ASSY-HEAD,RH	1.00	2210.00	20.00	1768.00
M WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80
M GEAR ASSY-STEERING	1.00	770.00	20.00	616.00
M HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80
M ARM COMPLETE-FR LWR,RH	1.00	286.00	20.00	228.80

# Estimate

Confirm & accepted by	DATE :	REMARKS :	Nett	8,650.00
LKK Auto Consultants hence notify the Repairer of the following:			7% GST on	8650.00
• To resurvey before/after spray painting			Total Payable	9,255.50
• To display damaged part(s) during resurvey				
• Parts prices are subject to confirmation				
• Third party survey is on a "Without Prejudice" basis				
• No illegal modification(s) to be allowed				
Authorized signatory and company stamp				

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SC0001 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD  
DATE & TIME: 28/12/2020 10:09 (SGT)  
REPORTED BY: TAN SHIEH YUEN  
POLICE REF: 1 (28/12/2020 10:09 (SGT))

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission  
Date of Accident  
Exact Location of Accident  
Additional Location Information  
Country/State of Loss

28/12/2020 10:09 (SGT)  
26/12/2020 17:30 (SGT)  
Senja Rd, Singapore  
SENJA ROAD  
Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SFA4832M

#### INSURED/POLICYHOLDER

Is company?  
Name Of Registered Owner  
NRIC No  
Email Address  
Mobile Phone No  
Alternative Phone No

No  
LEE MUN CHUNG  
SXXXX387E  
MUNCHUNG88@GMAIL.COM  
(Phone) +65-96271277  
+65-96271277

#### VEHICLE PARTICULARS

Manufacturer  
Model  
Variant  
Exact purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle?  
Vehicle Category

Kia  
Cerato  
-  
-  
Yes  
Private car

#### INSURANCE COMPANY

Name of Insurance Company  
Type of Coverage  
Fleet Policy  
Policy Number  
Cover Note Number

AIG  
Comprehensive  
No  
1900150620  
-

#### DRIVER

Name of Driver  
NRIC No  
Date Of Birth  
Occupation

LEE MUN CHUNG  
SXXXX387E  
21/11/1969  
Indoor

Driving Pass	12/07/1988
g experience	32 YEARS AND 5 MONTHS
der	Male
Mobile Number	(Phone) +65-96271277
Phone Number	+65-96271277
Email Address	MUNCHUNG88@GMAIL.COM
Address	BLK 474 SEGAR ROAD #13-306
Address complement	-
Postcode	670474
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	LIM SIEW LUAN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT  
COLLISION-HEAD TO SIDE

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SLV3550B
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	MOHAMAD SALIFUDDIN BIN OSEMAN

Number		(Phone) +65-97526787
Pass complement		
code		
Insurance Company Name		
Nature Of Damage		
Details of property damaged in accident		
No. Of Passenger (Including Driver)		

**IMPORTANT NOTICE**

- I understand, acknowledge, agree and consent that:

- Policyholder's Signature \_\_\_\_\_  
Date & Time: 28/12/2020 8:50 AM

CIA Rev. 5/20/94 Form 92

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

CH PLAN

Refer to attachment

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

09:00pm/28/12/2020

QIARAC SketchPlan form\_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





SFA4832M

Traffic light



Senja Road



SLV3550B

Senja Way



Traffic light

*Handwritten signature*

09.00 AM

28/12/2020

MUN CHIAO

EE



I (SFA4832M) was turning right from Senja Road traffic junction to towards Senja Way. Out of a sudden the (SLV3550B) was illegally using the right turn lane and drive straight, hitting my right front wheel of (SFA4832M). The road arrows shown both lanes can turn right at the traffic junction



0900 Am

28/12/2020

LEE MUN GUAN.

869403876

CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder  
Period of Insurance  
Engine No.  
Chassis No.

: LEE MUN CHUNG (LI MINZHONG)  
: 20 Aug 2019 To 19 Aug 2021  
: G4FGKH744191  
: KNAF3416MK5049787

Vehicle No. : SFA4832M  
Policy No. : 1900150620  
Endorsement No. :  
Issued Date : 29 Aug 2019

ABOUT THE COVER

Make/Model : KIA Cerato  
Engine Capacity/Tonnage : 1,591.00 CC  
Driver Restriction : NA  
Person or Classes of Persons Entitled to Drive\* :

Sum Insured : Market Value  
Off Peak Car : No

First Year of Registration : 2019  
Insuring with COE/PAF : Yes

a) The Policyholder  
b) Any other person who is driving on the Policyholder's order or with his/her permission.  
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LEE MUN CHUNG (LI MINZHONG) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278600
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622222

C&CKICP2 - WINYEO  
239 ALEXANDRA ROAD  
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*Manile*

AIG Asia Pacific Insurance Pte. Ltd.  
AUTHORISED REPRESENTATIVE

SSCZ98

1002526734/AC/Doc01

LO REG. INCORPORATED IN SINGAPORE | Copyright © 2019 AIG Asia Pacific Insurance Pte. Ltd.