



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO20014525/Uqd3q2 Date: 19/01/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 2356A	Veh. Inspected	YQ 197E
Policy No.	D20MTPCVE007183	Coverage (\$)	0.00
Claim No.	CMTD2003795/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	28/12/2020
2. Vehicle Particulars & Condition			
Make & Model	ISUZU NPR75 (A)	c.c	5193
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JAANPR75HJ7100262	Colour	WHITE
Odometer	33963 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/75 R17.5	GT RADIAL	7 mm
L/H Front Tyre	215/75 R17.5	GT RADIAL	7 mm
R/H Rear Tyre	215/75 R17.5 (D)	GT RADIAL	7/7 mm
L/H Rear Tyre	215/75 R17.5 (D)	GT RADIAL	7/7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/12/2020	Inspection Date	28/12/2020
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	