

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2020)

Parts: 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC8395Y/28/12/2020 13:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	20.00	0.00	*1,052.20 FL <i>dev</i>
2	1		*RADIATOR GRILLE	20.00	0.00	*1,480.00 FL <i>dev</i>
3	1		*RADIATOR GRILLE EMBLEM-H	20.00	0.00	*129.50 FL <i>dev</i>
4	1		*FRT BUMPER UPR BRKT LH	20.00	0.00	*22.40 FL <i>dev</i>
5	1		*FRT BUMPER SIDE BRKT LH	20.00	0.00	*24.60 FL <i>dev</i>
6	1		*FRT NO.PLATE WITH TRIM COVER	0.00	0.00	*55.00 FL <i>dev</i>

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 2,763.70

- List Item Discount on L Items (S\$) 541.74

Total Parts (S\$) 2,221.96

ComfortDelGro Engineering Pte Ltd/SHC8395Y/28/12/2020 13:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

2661.70

2129.36

55

2184.36

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

280

350.00

2 SPRAY PAINTING

New

200

250.00

Gross Labour Cost (S\$)

480

600.00

ComfortDelGro Engineering Pte Ltd/SHC8395Y/28/12/2020 13:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 9744 5749
'up' 28/12/20 5pm
02 days
45 Resurvey after repair
Tanpin e/Mark.com

2184.36

11

480

2675.36.

454 2150

02 days