

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305440835 Via Fax : Email  
Date : 26 12 2020 (Sat) Your Insured : SKE 9889L  
Time of Fax : \_\_\_\_\_ Date of Acc : 26 12 2020

Attn: Motor Claims Department

Dear Sirs

Atg Asia  
**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

C8452R  
Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident \_

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

♦ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
♦ <b>Lim Tien Siong</b>	Tel: 6214 8398 or HP: 9635 8546	
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
♦ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

**Lim Tien Siong**

for Vice President  
Crash Repairs & Claims Recovery

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 26.12.2020

Time: 10:52:57

Page: 1

(Sat)  
12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305440835  
REGN NO : SHC8452R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 03.12.2015  
DATE/TIME IN : 26.12.2020 08:50  
ACCIDENT DATE : 26.12.2020

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40
0002 04-01-0103-2934-A	FRT FENDER SHIELD RH	1	174.90	20.00	139.92
0003 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76
0004 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92
0005 04-01-0103-0640-G	FRT BUMPER SIDE BRKT RH	1	24.60	20.00	19.68

SUB-TOTAL : 1,549.68

## JOB NATURE

0000 PB	PANEL BEATING	300.00
0001 SP	SPRAYPAINT AFFECTED AREAS	500.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00

SUB-TOTAL : 840.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ang Bsr

Date: 26.12.2020

Time: 10:52:57

Page: 2

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305440835  
REGN NO : SHC8452R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 03.12.2015  
DATE/TIME IN : 26.12.2020 08:50  
ACCIDENT DATE : 26.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

UMP

TOTAL : 2,389.68

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	26/12/2020 10:12 (SGT)
Date of Accident	26/12/2020 08:00 (SGT)
Exact Location of Accident	9 Jln Membina, Singapore 169483
Additional Location Information	OPEN SPACE CARPARK
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC8452R

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-65508768
Alternative Phone No	(Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	I40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi

### INSURANCE COMPANY

Name of Insurance Company	India International
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	MCOM0015
Cover Note Number	-

### DRIVER

Name of Driver	DONG SUI HUNG
NRIC No	SXXXX197E

Date Of Driving Pass	14/05/1991
Driving experience	29 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96639333
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 16 SN MING WALK
Address complement	#10-01
Postcode	575568
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Other
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLS REFER TO ATTACHED  
Type of accident : 3P REVERSE

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE9889L
Vehicle Manufacturer	Volvo
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-98502978
Address	-
Address complement	-

Insurance Company Name .....  
Nature Of Damage .....  
Details of property damaged in accident .....  
No. Of Passenger (Including Driver) .....

AIG  
NO VISIBLE DAMAGE

-

-

**IMPORTANT NOTICE**


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**



I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **"Personal Information"**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **"Insurers"**), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the **"Purposes"**)
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared/disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

 26.12.2020  
Reporting Centre Personnel's Signature  
Name:  
NRIC/Fin No.: 

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 26/12/2020 at about 08:00 hrs, I Veh A went to
above said location to pick up oncall passenger.
I Veh A was stationary there, suddenly Veh B reversed out
from carpark lot and it rear portion collided onto the right
front portion of my taxi. I couldn't react to alert the driver
as it happen too fast. No injury at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: Loke Wei Yiong  
NRIC/Fin No.:

26.12.2020