

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Ang Hsian

(Sat)

Date: 26.12.2020

Time: 10:52:57

Page: 1

12 TS

ANY : THIRD PARTY'S CLAIMS (CAS)
OMER: 7010045

ESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305440835
REGN NO : SHC8452R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 03.12.2015
DATE/TIME IN : 26.12.2020 08:50
ACCIDENT DATE : 26.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

RT REQUISITION

001 04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40	h7	
002 04-01-0103-2934-A	FRT FENDER SHIELD RH	1	174.90	20.00	139.92	de	
003 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	RP	
004 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	X un	837.90
005 04-01-0103-0640-G	FRT BUMPER SIDE BRKT RH	1	24.60	20.00	19.68	X un	25% 670.32
SUB-TOTAL : 1,549.68							

JOB NATURE

0000 PB	PANEL BEATING	300.00	280	
0001 SP	SPRAYPAINT AFFECTED AREAS	500.00	400	710
0002 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30	
SUB-TOTAL : 840.00				

Tanphui 92445749
WP 12/12/20 c 4pm
2 days

Worthwhile.
1380.32
1/5 \$1100, 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2/5 Resurvey after repair
Tanphui C lkkauto.com