

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Re	f: CS/AGI20014571/Utd3q2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Da	te: 19/01/2021	
			Co	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLW 687E	Veh. Inspected	SLB 844D	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10008492/ST	Excess (\$)	0.00	
	Assign From	STANLEY LAI	Assign Date	28/12/2020	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA BIANTE (A)	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6CC1071G0109262	Colour	BROWN	
	Odometer	58493 KM	Steering	AFFECTED	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	MICHELIN	6 mm	
	L/H Front Tyre	205/60 R16	MICHELIN	6 mm	
	R/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
	L/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	26/12/2020	Inspection Date	29/12/2020	
	Survey held at	15 KAKI BUKIT ROAD 4# 01-53	1		
	Repairer	ZOOM AUTOWERKS PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: