

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI20014585/Kqd3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	09/07/2021	
			C	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLU 2239M	Veh. Inspected		SMP 1566P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008459/LA	Excess (\$)		0.00	
	Assign From	STANLEY LAI	Assign Date		28/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF5416MK5050537	Colour		GREEN	
	Odometer	25621 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/40 ZR18	PIRELLI		9 mm	
	L/H Front Tyre	225/40 ZR18	PIRELLI		9 mm	
	R/H Rear Tyre	225/40 ZR18	PIRELLI		9 mm	
	L/H Rear Tyre	225/40 ZR18	PIRELLI		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	23/12/2020	Inspection Date		29/12/2020	
	Survey held at YEE AUTO PTE LTD					
	160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: