

12/12/2020

REF: CS3/CTI20014587/Qvd3

Special Instruction:

ASS. REC. BY:

SURV BY:

ASSIGNMENT (Office)

Date/Time: 28/12/2020@3.09PM

Merimen

From (Person): TAN KAH LEONG

of CTI

Date/Time:

Estimated Cost:

Bill to:

OD: TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 5878Z

Insured: XE 4761A

at Workshop m/s ASSURE AUTO ASSIST

Tel: 6385 1171

of 14 AMK STREET 63 BLK B

Policy No: DMCVSNW00017042001

Claim No: SNM20D205086/C02/TANKI

Sum Insured:

Excess:

D.O.A. 23/12/2020

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.44PM@28/12/2020

Person Contacted: IRENE

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 5878Z-X
	XE 4761A-X
30/12/20	Submit PRS, repair range \$4,000-\$5,000 (4 days)